...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBI	FOLDER TRACK	ING										
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	j Submitted	Ins Auth'ed	Status				
Main	06 Apr 2022 07:34 Sendback Est	06 Apr 2022 08:03 S\$ 15,325.50	07 Apr 2022 11:29 Edit Adj Rpt					Pending for Survey Report Cancel Case				
CLAIM SUBI	FOLDER DETAI	LS										
Insured:	COMFORTDEL	GRO RENT-A-CA	R PTE LTD , Co	. Reg. No	.: 775H							
Vehicle Reg. No.:	SML5596Y	SML5596Y				oss : 02/04/2022 10:00 - :59 [34 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD				Policy/Cover Note No. :	D18MFL000	3414_02 (Compre	nprehensive)				
					Excess:							
Repairer:	ComfortDelGr	ro Engineering Pt	e Ltd (Braddell)) 205 Brad	dell Road, 57	ad, 579701 Toa Payoh - Tel: 63837613						
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 [Handled by Gabriel Wee - 63476100 ext 248]											
Adjuster:	LKK Auto Con	K Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Handled by KENNETH KONG] [Final Rpt due 19/04/2022]										
ASSOCIATE	D MAIL RECEIV	VED					Viev	v All Compose Case M				
There are no	mail for this case).										
No results.	IATED FILE NO	OTESE						Create N				
No. Status No results.	Vie	ewer/ signed Note					Created	On Created By By				
ADJUSTER'S	S CLAIM REFER	RENCE										
Assignment F	rom:	India Internati	onal Insurance	Pte Ltd (HQ)							
Adj File Ref N	o:	CS/III22003213,	/KQY3		Assignment [Date:	07/04/2022					
Inspection / Investigation Date:			-		Report Date:							
Insurance Cla	im No:				Recmd'ed Re	sv. (S\$):						
Manager:		SHIAU CHAN			Adjuster:	KENNETH KONG		ONG				
Clerical:		(First Pick-up)										
Present Vehic	le Loc.:	ComfortDelGro E	ingineering Pte Lt	d (Bradde	ll) (from est.)	(Check-in: 06	/04/2022)					
DESCRIPTION	ON OF VEHICLE											
Vehicle Model	:	TOYOTA PRIUS	1.8 5DR HATCH	HBACK (A	()							
Engine No:		2ZR2C23627			Chassis No:		JTDKB3FU70	JTDKB3FU703081009				
LTA Reg Date	(Man Yr):	27/05/2019 (20:	19)									
Colour of Veh	` '	White	•		Odometer Re	ading:	10000 km					
Joiodi of Verneie.							TOOOD KIII					

Party At Fault:

Nature of Loss:

TP Injury Involved?

Unknown

No

CLAIM LOSS DETAILSPolice Report No (Date):

Description of Accident/Loss:

Third Party Involved?

Private Vehicle

Yes

Collision With:

DOCUMENTS CHECKLIST	All Completed	Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: Repairer Handling Insurer				
Note: Remarks are private unless you show it to other parties.				
DOCUMENTS SUMMARY				
Video				
ComfortDelGro Engineering Pte Ltd (Braddell) [Thumbnails]:(06/04/22) Video - Accident				

• ComfortDelGro Engineering Pte Ltd (Braddell) [Thumbnails]:(06/04/22) Repairer Estimates

Assessment Reports

Documentation

ComfortDelGro Engineering Pte Ltd (Braddell) [Thumbnails]:(06/04/22) E-filed GIA report, Certificate of Insurance
 India International Insurance Pte Ltd (HQ) [Thumbnails]:(07/04/22) Singapore Accident Statement