

Surveyor:

REF: CS/LAW22003223/Kqc

Special Instruction:

ASSIGNMENT (Office)

From (Person): Lim Hui Ying of Legal Solutions Date/Time: 30/03/2022

Third Parties: LS \$4,450.00

Estimated Cost: _____ Bill to: _____

Claimant: Owner

OD **TP Re-inspection** / Evaluation

Surveyor: Auto Performance

To Inspect Vehicle No: SKR 3527C Insured: GBA 5711U

Workshop: Sze Kang Automobile

at Workshop m/s Sze Kang Automobile Tel: 8201 9979

of Blk 10 Ang Mio Kio Ind Pk 2A #03-17

Policy No: _____ Claim No: LIH/1023956/NTUC SJE

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06/12/2019
(Client's Record)

Appt Date: 11/04/2022 10.30am

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle **IN / OUT**

Date/Time: _____ Confirmed with _____ Final Fig _____, _____ days (Red \$ _____ / _____%; Original _____ days)

Date/Time: 13/04/22 Submit ~~Final Fig~~ LS \$1200, 3 days (Red \$ 3250 / 73%; Original 4 days)

Date/Time	Action/Instruction
	SKR 3527C - X
	GBA 5711U - X
	50/50 billing

Para(1) : **Parts found not replaced (To highlight R or UB, LR, Etc)**

Para(2) : **Comments on consistency of damages (Parts Not Consistent : NC)**

Para(3) : Nett Value

Market Value : _____
Salvage Value : _____
Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:
Basic & Add
Transport
Photos
Others
Total

Date:

- 1) Date/Time 13/04/22 File Pass to Typist
- 2) Date/Time _____ File Return to _____
- 3) Date/Time _____ File Pass to _____
- 4) Date/Time _____ File Return to _____
- 5) Date/Time _____ File Pass to _____
- 6) Date/Time _____ File Return to _____