



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003245/Uty3n2 Date: 23/05/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 8027U	Veh. Inspected	SML 5533D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014578/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	07/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	SKODA OCTAVIA RS (A)	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	TMBBU7NE1K0065789	Colour	WHITE	
Odometer	59499 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	GOODYEAR	7 mm	
L/H Front Tyre	235/40 R18	GOODYEAR	7 mm	
R/H Rear Tyre	235/40 R18	GOODYEAR	7 mm	
L/H Rear Tyre	235/40 R18	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2022	Inspection Date	29/04/2022	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	