

ASS. REC. BY: AnnaREF: CS/CT122003252/Rty3

589E

ASSIGNMENT

COT 12/24/2026/NOV

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 25646at Workshop m/s WAT HONGof 38, 10TH ANNIVERSARY #01-57Insured: CT

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 45K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: YN 25646Yr Regn: 2011 / NOVType: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI FE83B60c.c 2977Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: 418158

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FE83B6A20731Gen. Cond: Good (Fair) / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 7.00R16R: 185R14C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 6/6 mmL/Bal. 7 mmL/Bal. 6/6 mmD.O.A. 06/04/22D.O.I. 08/04/22Survey held at WAT HONGDes. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 26Kcost of repair of L/S \$24,800.00 /- with 17 days of repair, subject to their approvalRED: 19693.60;44%

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 17

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL

Rep. Format: _____

Lump Sum / L.S. (\$) _____



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg (199806235M)

Vehicle No. YN2564G MITSUBISHI CANTER FE83BEOSRDEA

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
2	Front door LH/RH @2*\$2038 <i>LH-bt / RH-require</i>		4076	
2	Front door trim board LH/RH @2*\$638 <i>de</i>		1276	
1	Front bumper <i>bt</i>		986	
1	Center grille <i>cm</i>		599	
1	Center grille logo badge <i>cm</i>		85	
1	Center grille emblem "fuso" <i>mis</i>		160	
1	Front panel <i>bt</i>		1636	
1	Front inner upper panel ?		2032	
2	Front panel side panel LH/RH @2*\$584 <i>de</i>		1168	
1	Wiper garnish <i>de</i>		454	
1	Wiper garnish sticker "canter" <i>cm</i>		124	
2	Wiper arm LH/RH @2*\$138 <i>bt</i>		276	
1	Side mirror rh <i>bt</i>		101	
1	Side mirror arm rh <i>bt cut</i>		584	
1	Side mirror arm panel garnish rh <i>cm</i>		389	
1	Side mirror arm panel top garnish rh <i>bt</i>		55	
1	Side mirror Lh <i>cm</i>		101	
1	Side round mirror Lh <i>mis</i>		56	
1	Side mirror arm lh <i>bt</i>		422	
1	Side mirror arm top round cover lh <i>mis</i>		20	
1	Side mirror arm panel garnish lh <i>cm</i>		389	
1	Side mirror arm panel top garnish rh <i>cm</i>		55	
2	Signal lamp LH/RH @2*\$227 <i>cm</i>		454	
2	Headlamp LH/RH @2*\$635 <i>cm</i>		1270	
2	Side lamp LH/RH @2*\$159 <i>cm</i>		318.00	
1	Tail door <i>bt</i>		2058.00	
2	Tail door hinge LH/RH @4*\$190 X		760.00	
2	Tail door lower lock latch LH/RH @2*\$195 X		390.00	
2	Tail lamp LH/RH 2*\$229 X		458.00	
1	Rear car plate lamp X		60.00	
1	Tail door upper latch LH/RH @2*\$180 X		360.00	
1	Aircon pipe high pressure <i>bt</i>		290.00	
1	Aircon pipe Low pressure <i>bt</i>		280.00	
1	Cabin front support bar <i>bt</i>		1043.00	
1	Cabin front support bar side bracket RH <i>bt</i>		787.00	
1	Cabin front support bar side bracket LH <i>bt</i>		851.00	

2	Cabin front bar side bracket bush LH/RH @2*\$208 <i>des</i>	416.00			
1	Dashboard ?	1085.00			
1	Roof lining <i>de</i>	808.00			
1	Front floor panel <i>repair</i>	1791.00			
1	Front cabin rear panel <i>repair</i>	1648.00			
1	Front windscreen <i>can</i>	1132.00			
1	Front windscreen rubber <i>re</i>	493.00			
1	Rear window glass <i>br</i>	204.00			
1	Rear window glass rubber <i>re</i>	196.00			
1	Heater assy ?	3517.00			
1	Blower assy ?	1012.00			
1	Front door pillar LH/RH (Repair refer to labour)	0.00			
1	Front cabin rear support railing (Repair refer to labour)	0.00			
		36725.00			
		-10% -3672.50			
		33052.50			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Patru
Hp 90010068
17 days
L/S
08/04/22 @ 1500
Reay after repair



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. YN2564G MITSUBISHI CANTER FE83BEOSRDEA

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	2000.00	1400
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00 40	60
4	To perform anti-rust treatment on affected areas	90.00 60	
5	To remove and replace air-con condenser, pipes, vacuum and recharging gas	120.00 80	
6	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00 60	
7	To remove and refit/replace Front door RH fitting, trimmings, garnish, window glass and lock mechanism	120.00 60	
8	To remove and replace front windscreen	150.00 120	
9	RED: 19693.60 To remove and refit dashboard and related wire harness and related parts	300.00 150	plh?
10	To remove, replace and focus headlamp beam	60.00 30	
11	To remove and replace cabin rear windscreen	100.00 60	
12	To remove and replace roof lining	200.00 80	
13	To remove and replace cabin front bar with both side bracket	400.00 150	
Labour Total :		5750.00	
TOTAL (PARTS & LABOUR):		40382.50	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/04/2022 12:15 (SGT)
Date of Accident	06/04/2022 08:00 (SGT)
Exact Location of Accident	Near 17 Joo Koon Cir, Singapore 629049
Additional Location Information	FIRST LOK YANG RD TO AYE EXPRESSWAY TWDS TUAS SHIPYARD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN2564G
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DOUBLE S CONSTRUCTION PTE LTD
Company Reg No	2XXXXX599E
Email Address	admin@doublesconstructions.com
Mobile Phone No	(Phone) +65-98870900
Alternative Phone No	(Office) +65-62644752

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Canter
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2998

INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	No
Policy Number	2021-V0116783-VCV
Cover Note Number	-

DRIVER

Name of Driver	ANTHONY JOSHWA
----------------	----------------

Work Permit No
 Date Of Birth
 Occupation
 Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

GXXXX391R
 01/07/1996
 Outdoor
 01/10/2019
 2 YEARS AND 6 MONTHS
 Male
 (Phone) +65-81200445
 -
 antonyjoshwa01@gmail.com
 13 KIAN TECK LANE
 BLUE STARS DORMITORY
 627849
 No
 Employee
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 3
 Was anybody injured in the Accident? Yes
 Was any injured conveyed to hospital by ambulance? No
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? Yes
 Police Station Name Nanyang Neighbourhood Police Centre
 Police Station Phone No (Phone) +65-18007929999
 Alt. Police Station Phone No (Fax) +65-67912972
 Police Station Address No. 2 Jurong West Avenue 5 Singapore 649482
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT T/20220407/2025

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? No
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number PA9817G
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -

Vehicle Category	Bus
Name of Driver	LIM KIAN BENG
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	XE9989C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ANTHONY JOSHWA
Gender	Male
Phone No	(Phone) +65-81200445
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BACK AND RIGHT SHOULDER INJURIES
Injured person in which vehicle?	YN2564G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

A. J. J. J.


Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan

AYE BEFORE
EXIT BEND!
RD.



A: YN2564G
B: PA9817G
C: XE9989C



SINGAPORE POLICE FORCE



T/20220407/2025

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 3

Report No. T/20220407/2025

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/04/2022 10:46		Vide Report No.:		Station Diary No.: 25	
Informant's Particulars					
Name of Informant: ANTHONY JOSHWA			Address:		
ID Type / ID No.: FIN NO / G2837391R			Contact No.: Home/Office: Mobile: 81200445		
Nationality: INDIAN			Email: antonyjoshwa01@gmail.com		
Sex: Male	Age: 25	Date of Birth: 01/07/1996	Type of Informant: Driver		
Race: Indian		Language:		Institution / School Name:	
Occupation: Lorry driver		Driving Licence Information: Class: 3 Date of Expiry: 30/09/2024			

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/04/2022 08:00	Type of Location: Expressway
Location: AYER RAJAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
PA9817G	Bus/Coach/Mi nibus				Slightly Damaged	3
XE9989C	Lorry				No Damage	0
YN2564G	Lorry				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20220407/2025

2 of 3

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20220407/2025

CONTINUATION OF REPORT

Driver			
Name	LIM KIAN BENG	ID No.	S1386333D
Related Vehicle	PA9817G (Bus/Coach/Minibus)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ANTHONY JOSHWA	ID No.	G2837391R
Related Vehicle	YN2564G (Lorry)	Contact No.	81200445
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: 30/09/2024
Date Treatment	06/04/2022	Date Discharge	06/04/2022
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 06/04/2022 at about 0800hrs, I was driving my lorry bearing vehicle registration number YN2564G from First Lok Yang Road to AYE Expressway towards Tuas Shipyard on the third lane. I was driving in between a lorry bearing vehicle registration number XE9989C (in front of me) and a bus bearing vehicle registration number PA9817G (behind me). The traffic was very heavy, everyone was driving very slowly. As I saw the front lorry braking, I too used my brake but only to move slow and not to stop and suddenly the bus behind me hit my lorry at the rear which cause a chain of accident between the three of us. The bus had hit my lorry and cause my lorry to move forward and hit the lorry in front. I suspected that the bus hard braked and hit my lorry. We all came out of our vehicles and wanted to exchange particulars however the lorry driver in front of me refused to give me his particulars as he told me that the bus driver is at fault and should only ask from him. I am not sure how many people inside the bus as only the bus driver came out. No police or ambulance came to scene. No government property damage. My lorry sustained some damages to the front, body, and rear. The lorry did not sustain any damages and the bus has some damages to the front. I am not sure if they are injured. I sustained some injuries to my back and my right shoulder which caused me to visit the clinic at Pioneer Medical Centre which referred me to the hospital at Ng Teng Fong General Hospital. My lorry had no dash camera installed.



SINGAPORE POLICE FORCE

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999



T/20220407/2025

3 of 3

Report No. T/20220407/2025

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

J /

SCCPL MUHAMMAD FIKRI BIN
JOHARI

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /
SI TAN JEOK LENG
Contact No.: 65476151

NP168

Signature Of Informant:

Date/Time:

07/04/2022 10:46

Classification Of Case:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

599E

Vehicle No.:

YN2564G

Vehicle to be Exported:

Yes

Intended Deregistration Date:

06 Apr 2022

Vehicle Make:

MITSUBISHI

Vehicle Model:

FE83BEOSRDEA

Primary Colour:

White

Manufacturing Year:

2011

Engine No.:

4M42A88576

Chassis No.:

FE83BEA20731

Maximum Power Output:

-

Open Market Value:

\$33,632.00

Original Registration Date:

10 Nov 2011

First Registration Date:

10 Nov 2011

Transfer Count:

4

Actual ARF Paid:

\$1,682.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

09 Nov 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$20,083.00

COE Rebate Amount:

\$18,442.00

Total Rebate Amount:

\$18,442.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 06 Apr 2022

OK

Mitsubishi Fuso Canter FE83 (COE till 09/2026)

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

Price	\$45,800	Lifespan ⓘ	04-Oct-2031
Depreciation ⓘ	\$10,240 /yr	Reg Date	05-Oct-2011 (4yrs 5mths 19days COE left)
Mileage	126,500 km (12k /yr)	Manufactured ⓘ	2011
Road Tax ⓘ	N.A.	Transmission	Manual
Dereg Value ⓘ	\$17,525 as of today (change)	Fuel Type	Diesel
COE ⓘ	\$19,586	OMV ⓘ	\$33,054
Engine Cap	2,977 cc	ARF ⓘ	\$1,653
Curb Weight ⓘ	2,360 kg	No. of Owners	1
Type of Vehicle	Truck		