ASS	IGNMENT
From: Date:	Veh No: St 71868-1 Yr Regn: 23/12/09
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or (A/
o Inspect Vehicle No: $S \leftarrow 7/F6FJ$	Make: Teysta Estima Aerasco 2362
t Workshop m/s Usia Motorszof.	Colour Slock A/C: Insured / Std / NI / NA
f	Sp.Reading 23 27 T/Radio: Insured / Std / NI / NA
nsured: SG 1699 R	Eng/No:
Policy No.	C/No: ACR 500104463
Claims No. BUS/04/22/7001	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Incorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 215 / 60 R 17 Continente
(Policy Condition)	R: Dunlop
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 1 mm R/Bal. 1 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 3 mm L/Bal. 3 mm
Est. Repairs: O days Res.: Yes or No	D.O.A. 05/04/22 D.O.I. 8/4/27
_um Sum: 20 % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 4 23 h	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT  Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted: Dep 9 (2.	The O/C / Chassis frame / Body Structure affected due to comsion.
COLUMN 22-12-2029-17A=3	.0287
22 2/5 \$ 7300 informed At	(red 19,646.83, 72%)
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
: Final Report	Resurvey No. of Trip: 2 Survey Fee:
Date/Time, File Return to?	Transportation:  (\$ )S + RS,SI
4/5/00 / · · ·	
2) 4/5/22-typist Add Fe	
, 3. <u></u> 3, p. 3.	: Interview (\$ ) Photos
2) 4/5/22-typist Add Fe  Report Format : TP  Lump Sum / <del>I.B.l.</del> (\$ 7300	

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	423H
Vehicle Details	
Vehicle No.:	SLT1868J
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS 2.4 A
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	2AZC763776
Chassis No.:	ACR500104463
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$35,972.00
Original Registration Date:	23 Dec 2009
First Registration Date:	23 Dec 2009
Transfer Count:	4
Actual ARF Paid:	\$35,972.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$39,313.00
COE Rebate Amount:	\$30,287.00
Total Rebate Amount:	\$30,287.00

The information contained herein is correct as at 08 Apr 2022

OK

### SGCARMART.COM

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

**Products** 

Insurance

Articles

Forum

Resources

NEW Cancer-Sourced Blood Products EXPLORE NOW >

2018 Ford Focus 1.0A GTDI Titanium @ \$68.8k

Post an Advertisement Sell it yourself! Advertise it at just

\$68 until it's SOLD!



romo! Interest Rate @ 1.88% Trust Motoring StarAd

HIN LUNG AUTO One Stop Car Hub Finance, Insurance, Workshop New and Used Cars

Sort by Date Posted V 20 V results/page

15 vehicles

Post an Ad

estima 2029 Any Category Advanced Search Search

Search Selection

Advertiser Login

Model

Ways of Selling

Price

Depreciation

Reg Date Eng Cap Mileage

Veh Type

Make

estima 2029

Any

Any

> 10 year(s) old

Any

Any

Available Any

Toyota Estima 2.4A (COE till

\$70,000

\$9,480 /yr

\$888 Monthly. 2.88% Per Annum By GV Cars Financing! \$0 Downpayment Available! Add On, 2 Years Warranty On Engine And Gearbox...

25-Aug-2009

2,362 cc

MPV

Available

GV Automobile Centre Pte Ltd

Posted: 08-Apr-2022

\$68,800

\$9,740 /yr

12-May-2009

2,362 cc

142,580 km

Available

Toyota Estima 2.4A Aeras Moonroof (COE till 04/2029)

Pristine Condition! Low Mileage, No Repairs Needed, Fully Done Up, Full Loan/Bank Loan Available, No Hidden Fees Involved! High Trad...

Posted: 08-Apr-2022



Toyota Estima 2.4A Aeras Moonroof (COE till 09/2029) \$75,800

\$10,140 /yr

28-Sep-2009

2,362 cc

160,000 km

Available

PREMIUM AD

Superb Well Maintained Sliver Estima! Toyota Luxury Sliding Doors MPV! All Wear And Tear Done Up. Well Maintained By The Previous...

1axis

Posted: 07-Apr-2022



Toyota Estima 2.4A Aeras

Moonroof (COE till 01/2029)

\$63,888

\$9.370 /vr

12-Feb-2009

2.362 cc

156,968 km

MPV

Available

2 Owners Only. Bank loan interest at 2.88% to 3.18%! Full loan scheme available at only 3.98%. Wear & tear recently replaced. Gearbo...

Posted: 06-Apr-2022



Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



Toyota Estima 2.4A X 8-Seater (COE till 10/2029)

\$75,800

\$10,030 /yr

28-Oct-2009

2,362 cc

134,348 km

MPV

Available

100% Loan Available. Toyota Luxury Sliding Doors MPV! All Wear And Tear Done Up, New Paintwork Done. Well Maintained By The Prev..

Posted: 05-Apr-2022



Toyota Estima 2.4A G (COE till 01/2029)

\$68,800

\$10,130 /yr

22-Jan-2009

2,362 cc

139,000 km

Available

Posted: 04-Apr-2022

SA1E22460001 / Abwin Service Pte Ltd ENTRY DATE & TIME: 06/04/2022 17:12 (SGT) SUBMITTED BY: Gerine Cheng VERSION: 1 (06/04/2022 17:12 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
   By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission 06/04/2022 17:12 (SGT) Date of Accident 05/04/2022 07:35 (SGT) **Exact Location of Accident** TPE, Singapore Additional Location Information TPE TOWARDS PIE (CHANGI) Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Toyota

Vehicle Registration Number SLT1868J

#### INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LOH KUI KENG NRIC No SXXXX423H Email Address ANDREAHOI@SFLEASING.COM.SG Mobile Phone No (Phone) +65-98269944 Alternative Phone No (Home) +65-98269944

#### VEHICLE PARTICULARS

Manufacturer

Model Estima Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 2362

### **INSURANCE COMPANY**

Name of Insurance Company NTUC Income Insurance Co-operative Ltd Type of Coverage Comprehensive Fleet Policy No Policy Number 5120147369-01 Cover Note Number

DRIVER

Daté Of Birth	31/01/1971
Occupation ::	Outdoor
Date Of Driving Pass	25/03/1992
Driving experience	30 YEARS AND 1 MONTH
Gender	Male
Mobile Number	
Alt. Phone Number	(Phone) +65-96576387
	-
Email Address	BHKASSIMJ@YAHOO.COM
Address	95 PASIR RIS GROVE
Address complement	#01-42
Postcode	518192
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Friend
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
· · · · · · · · · · · · · · · · · · ·	_
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry
	Diy
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s)	2
soliciting/offering accident claims assistance?	No
PASSENGER 1	
Name	ROZITA MUHAMAD SAH
Gender	
Gender	Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	
If yes, against whom?	No -
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKTECH PLAN ATTACHED	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	
was there any video captured by Car Carriera?	Yes
Was there any video captured by Car Carriera?  Was there any audio recorded?	Yes No

31/01/1971

DETAILS OF OTHER VEHICLE PROPERTY 1

-----

\ / - |- : - | - | - - : - a.. - a! - .. | **k** | . . . . | . . . .

Date Of Birth

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKK808Z
Vehicle Manufacturer	Toyota
Vehicle Model	Estima
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	

# DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJX6230T
Vehicle Manufacturer	Mazda
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

# INJURED PERSONS DETAILS

# INJURED 1

Name of injured person	BADRUL HISHAM BIN KASSIM
Gender	Male
Phone No	(Phone) +65-96576387
Address	95 PASIR RIS GROVE
Address Complement	#01-42
Post Code	518192
Approximate Age Years Old	51
Injuries Sustained	3 DAYS MC
Injured person in which vehicle?	SLT1868J

# INJURED 2

Name of injured person	ROZITA MUHAMAD SAH
Gender *	Female
Phone No	(Phone) +65-85696560
Address	-
Address Complement	
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	
Injured person in which vehicle?	SLT1868J
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes
INJURED 3	

NJONED 3	
Name of injured person	BUS DRIVER
Gender	Male
Phone No	5.
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SG1699R
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

escribe Circumstances of the Accident On the Stated date & time I was travelling
straight along TPE towards PIE (charge). Suddenly
I feet a huge impact and realised it was webico
B collided to vehicle C and vehicle D and my
Vehicle. Due to vehicle B sudden stope can't
control the newcie, caused the pushed wehich
C to left and vehicle D pushed to right and
collided to rear portion of my vehicle.
I wish to state that accident video attached
Declaration
We declare the foregoing particulars are true in every respect

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2 This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withtening of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any falso reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the inscrees of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the tedgerrant of this report to the insurers, you hereby consent to the arctiving of this report at the centre and to copies of the report being made available afcresaid
- 8. Consent under the Personal Data Protection Act (PDPA)

Tunderstand, acknowledge, agree and consent that

(a) My inserer , my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal detailpersonal information set out in this [found and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information or unable to me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) knowed in this accident shall be collectively referred to as the "This unders"), the insurers law years flow inns, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(ii) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary accessigations relating to the cisins

to avestgating the accident and/or my claims

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.

By) administering my claims (behaling the naking of correspondence, statements, aveaces, reports or notices to are, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of provide personal. packages); and/or

(v) ecopying with applicable law in administering, processing handling and/or cleaking with my claims

(collectively the "Purposes")

(ti) at insurer(s) who have issured vehicle(s) involved in this accident and the haurers' lawyers/law firms, my/ann pendited to collect ase, recinse ander process my Personal Morrodion for one or more of the above Reposes; and

(c) my Porsonal information may/can be disclosed by any of the losuxers analor GA to their third party service provide SERVIC

(including their tawyershaw firms), which may be sited outside of Sagapore, for one or more of the above Funcese

Policyhokler's Signature / Dato &

Sketch Plan

ire (if driver is not the policyholder) / Date Orbital's Signi

Witnessed by Regarding Centre

2013186850

Personnal

Velacle n: St 1868] VELLECUE B: SIG 1699 R

velicu C: Stk. 808 Z

Vehicle 0: 93x 6>30 T

Not Authorizad Leu 8/4/22 2/547300/ 6days.

# SLT1868J Toyota Estima

No	On	Parts Developing	1	Estimated:
1	1	Rear bumper assy 215 628:10	\$	1,581.60
2	2	Rear bumper bracket WS	\$	173.20 X
3	1	Rear left bumper side end retainer CC2	\$	90.60
4	1	Rear right bumper side end retainer 11	\$	90.60 ⊀
5	1	Rear left bumper side retainer CAR	\$	88.50
6	1	Rear right bumper side retainer	\$	88.50 X
7	2	Rear bumper reflector V/S (12 105.03	\$	286.70 12
8	1	Rear left bumper tow hood cover Rear left bumper tow hood cover	\$	44.40
9	1	Rear right bumper tow hood cover 11	\$	44.40 ×
10	1	Rear bumper left side sponge Torn 145.50	\$	171.10
11	1	Rear bumper right side sponge	\$	171.10 X
12	1	Rear tailgate assy 1485.10	\$	2,812.60
13	1	Rear tailgate inner board De /7000	\$	494.10
14	1	Rear tailgate lock mechanism po /Jm	\$	581.40
15	1	Rear tailgate lock catch 11	\$	86.30
16	1	Rear tailgate lock switch	\$	164.10 ×
17	1	Rear tailgate centre logo	\$	68.80
18	1	Rear tailgate 'Estima' emblem	\$	66.60
19	1	Rear tailgate 'Aeras' emblem	\$	65.40
20	2	Rear tailgate hinges	\$	392.80 ×
21	2	Rear tailgate dampers 17	\$	596.20 >
22	1	Rear tailgate weatherstrip $1 \sim 1$	\$	288.20
23	1	Rear tailgate outer garnish (~	\$	181.50
24	2	Rear tailgate number plate lamp 11	\$	180.60 X
25	1	Rear tailgate inner handle	\$	121.30 X
26	1	Rear tailgate center lamp	\$	299.40
27	1	Rear tailgate left taillamp C/ 345, 10	\$	435.30
28	1	Rear tailgate right taillamp (% 345-16)	\$	435.30
29	1	Treat territaria	\$	787.50
30	1	real right turnamp	\$	787.50 ×
31	1		\$	781.60 X
32	1	Rear end lower outer panel Body D	\$	887.40
33	1	Rear end lower panel top garnish D()	\$	284.20
34	1	Rear end lower panel inner garnish D	\$	191.50
35	1	Rear windscreen glass moulding 166-10	\$	288.80
36	1	Rear floor panel	\$	1,681.70
37	1	Rear floor panel top cover Suc	\$	$226.30 \times$

SLT1868J Toyota Estima

	8J Toyota Estima	Estimated
	y Parts Description	Parts Price
38 1		\$ $3,306.10 \ \lambda$
39 1	, and the second control of the second contr	\$ 3,306.10 ×
40 1	Smith 2 / 1	\$ 445.10
41 1	V()	\$ 445.10 X
42 1	V( )	\$ 188.80 X
13 1	Rear right fender inner cowling	\$ 188.80 🗴
144 1	Rear left quarter glass moulding $47$	\$ 88.80 X
15 1	Rear right quarter glass moulding	\$ 88.80
16 1	Rear exhaust muffler assy	\$ 1,289.10 X
7 2	Rear exhaust muffler rubber mounting 11	\$ 88.60 X
18 1	Rear wiper motor $\wedge \wedge$	\$ 287.10 X
19	Rear wiper blade $\land \land$	\$ 109.60 ×
		\$ 25,849.10
	less 25%	\$ 6,462.28
		\$ 19,386.83
150	4 Special Nett Items	
1 12	Rear bumper clips	\$ 60.00
2 13440	Rear tailgate inner board clips	\$ 50.00 L
3 4	Rear tailgate outer garnish clips	\$ 40.00 🗴
4 1	Rear end lower inner panel sealant	\$ 120.00 ×
5 1	Rear end lower outer panel sealant	\$ 120.00
6	Rear end lower panel top garnish clips 11	\$ 40.00 X
7 6	Rear end lower panel inner garnish clips	\$ 40.00
3 1	Rear windscreen glass sealant	\$ 100.00 4
) /8ag	Rear bumper reverse sensor Shall	\$ 300.00 20
0 1	Rear no plate with garnish	\$ 100.00 ×
1 /seeff	Rear view camera shotel	\$ 450.00 30
2 1	Rear floor panel sealant	\$ 150.00 🗸
3 1	Rear floor panel insulator pad	\$ 180.00
4 1	Rear left fender sealant	\$ 100.00 🗙
5 1	Rear right fender sealant	\$ 100.00
6 4	Rear left fender inner cowling clips 17	\$ 30.00
7 4	Rear right fender inner cowling clips 1	\$ 30.00
8 10	Rear left fender inner garnish clips	\$ 40.00
9 10	Rear right fender inner garnish clips	\$ 40.00
0 1	Rear left quarter glass sealant 1	\$ 80.00
1 1	Rear right quarter glass sealant	\$ 80.00 X
		\$ 2,250.00
	Total parts	\$ 21,636.83

# SLT1868J Toyota Estima

	一个一个生态的特殊。 1		Labour	
No	Description 5 4 4		Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area	\$	2,000.00	1100
	and replace rear damaged parts including floor panel.			
2	To putty and spray painting rear portion.	\$	2,000.00	1100
3	To check rear lighting and wiring.	\$	50.00	30
4	To remove and install rear tailgate lock mechanism.	\$	80.00	6,2
5	To remove and install rear exhaust muffler assy.	\$ /	120.00	X
6	To remove and install rear fuel tank to facilitate the repair.	\$ 1	180.00	X
7	To remove and install rear inner garnish and trim to facilitate the	\$	180.00	20
	repair.			0,
8	To apply anti rust proofing to rear affected area.	\$	140.00	80
9	To remove and install rear bumper reverse sensor.	\$	80.00	50
10	To remove and install rear windscreen glass to facilitate the repair.	\$	140.00	120
11	To remove and install rear view camera.	\$	80.00	40
12	To remove and install rear left quarter glass.	\$ >	11 80.00	X
13	To remove and install rear right quarter glass.	\$1	80.00	X
14	Towing service.	\$1	100.00	X
	Total labour :	\$	5,310.00	

**Total parts:** \$ 21,636.83 **Total labour:** \$ 5,310.00 Total repair cost: \$ 26,946.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date:

1-7842.20 2572 P5881.65 5.N-690 2-2660 4-2660 731.65