

ASS. REC. BY: Kenneth

HLA


CS/HLA22003267/Kny3

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Chen Com  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: 250  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 44K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 05 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S/C 7052X Yr Regn: 05, 16  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: NIS Note C.G. 1198  
 Colour: M. Gray A/C: Insured / Std / NI / NA  
 Sp. Reading: 97369 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JN1TAAE1280972272  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rlm / STD / Rlm, or  
 Tyre Size: F: 185/85R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>8</u> mm
D.O.A. <u>2/4/22</u>	D.O.I. <u>8/4/2022</u>

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>lump sum: \$2750 and 5 days</u> <u>(red, \$3010.70/52%)</u>

Date/Time, File Pass to?

☐ : Prell. Report  
☐ : Final Report

Days Of Repair: 5

1) 15/08/22

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

\$ + RS. \$ \_\_\_\_\_

Furnish

Others

Report Format :

Lump Sum / I.B.I: (\$) 2750

TOTAL

ASS. REC. BY: \_\_\_\_\_

REF: 1/4/22 17.00.00.00

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: HL Assurance Pte Ltd

Accident Date : 02.04.2022

Not Authenical  
11 Ring @  
Penny After Penny  
Ex \$250h

5 days

MP309831

Policy No:

07.04.2022

Date:

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
<b>Estimate Cost Of Repair To "Nissan Note" Reg. No SLC7052X</b>			
1pc	Front Bumper		250.00
12pcs	Front Bumper Clips	2.00	24.00
1pc	Front Bumper Bracket		150.00
2pcs	Front Bumper Top Retainers	20.00	40.00
1pc	Front Bumper Reinforcement		185.00
2pcs	Front Bumper Corner Retainers	25.00	50.00
1pc	Front Bumper Top Nose Panel		135.00
1pc	Front Bumper Sponge		120.00
1pc	Grille		155.00
1pc	Grille Emblem		45.00
2pcs	Headlamp Assy	350.00	700.00
1pc	Front Fender LH		265.00
1pc	Front Fender Shield		65.00
1pc	Front Fender Quart Glass Moulding		185.00
1pc	Support Panel		250.00
1pc	Radiator		400.00
1pc	Radiator Expansion Tank		65.00
1pc	Air Con Condenser		380.00
1pc	Air Con Condenser Side Air Guide LH		35.00
1pc	Air Con Condenser Lower Air Guide		35.00
	Cost Plus 5%		3,534.00
			176.70
			3,710.70
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Remove / Refit Air Con Condenser & Refill Air Con Gas by Repairer		120.00
	To Conduct Computerize Wheel Alignment Test		80.00
	To Provide Transportation (Towing)		120.00
	Labour Charge - Panel Beating, Repairing of Bonnet, Front Chassis Member, Front RH Fender, LH Fender Inner Panel etc.Cnt, Weld Support & Part Replacement		800.00
	To Respray Affected Areas		900.00
	<b>Total :</b>		<b>5,760.70</b>

**LKK Auto Consultants hence notify  
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

(Bill)

7201



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 04/04/2022 10:21 (SGT)  
Date of Accident ..... 02/04/2022 15:20 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... POH HUAT ROAD WEST AND PARK VILLAS TERRACE  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLC7052X

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... TAN TECK TUAN VINCENT  
NRIC No ..... SXXXX034F  
Email Address ..... VITANTT@YAHOO.COM.SG  
Mobile Phone No ..... (Phone) +65-97592453  
Alternative Phone No ..... +65-97592453

#### VEHICLE PARTICULARS

Manufacturer ..... Nissan  
Model ..... Note  
Variant ..... NISSAN / NOTE 1.2 CVT ABS D/AIRBAG 2WD 5DR  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... Yes  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1198

#### INSURANCE COMPANY

Name of Insurance Company ..... HL Assurance Pte Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... MP309831  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... TAN TECK TUAN VINCENT  
NRIC No ..... SXXXX034F

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan





### Describe Circumstances of the Accident

I WAS COMING OUT OF ~~PO~~ PARK VILLAS TERRACE AND TURNING RIGHT INTO POH HUAT ROAD WEST. AS I STOPPED AT JUNCTION TO CHECK FOR TRAFFIC ON BOTH RIGHT AND LEFT SIDE. I THEN TURN RIGHT INTO POH HUAT ROAD WEST WITHOUT NOTICING AN ONCOMING VEHICLE ON MY LEFT. AS I TURN BOTH OUR CARS (SLM1144B) COLLIDED. THERE WAS NO HONKING OR SCREECHING OF TYRES. BOTH VEHICLES ARE PROBABLY QUITE SLOW.

### Declaration

We declare the foregoing particulars are true in every respect.

## Require PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

### Vehicle Details

034F

Vehicle No.:

Vehicle to be Exported:

SLC7052X

Intended Deregistration Date:

No

Vehicle Make:

04 Apr 2022

Vehicle Model:

NISSAN

Primary Colour:

NOTE 1.2 CVT ABS D/AIRBAG 2WD 5DR

Manufacturing Year:

Grey

Engine No.:

2016

Chassis No.:

HR12185733B

Maximum Power Output:

JN1TAAE12Z0972272

Open Market Value:

58.0 kW (77 bhp)

Original Registration Date:

\$13,026.00

First Registration Date:

24 May 2016

Transfer Count:

24 May 2016

Actual ARF Paid:

0

### Intended PARF Rebate Details

PARF Eligibility:

\$5,000.00

PARF Eligibility Expiry Date:

Yes

PARF Rebate Amount:

23 May 2026

### Intended COE Rebate Details

COE Expiry Date:

\$3,500.00

COE Category:

23 May 2026

COE Period(Years):

A - Car up to 1600cc & 97kW (130bhp)

QP Paid:

10

COE Rebate Amount:

\$47,300.00

Total Rebate Amount:

\$19,555.00

\$23,055.00

The information contained herein is correct as at 04 Apr 2022

OK