

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC22003299/Vtcn2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	06-05-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SLU 7668A	Veh. Ir	nspected	SHC 2484M	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1167765-002	Exces	s (\$)	0.00	
	Assign From		Assig	n Date	07/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2019	
	Chassis No.	KMHC851CVKU140904	Colou	r	BLUE	
	Odometer	266745	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST	LAKE	5 mm	
	R/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
	L/H Rear Tyre	195/65 R15	WEST	LAKE	5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	06/04/2022	Inspec	tion Date	07/04/2022	
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					