

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                |       |                       |
|---|--|---|----------------|-------|-----------------------|
|   | ALLIANZ INSURAN  | ICE SINGAPORE PTE LTD   |                | Ref:  | CS/AIS22003304/Avy3e2 |
|   | 79 ROBINSON RO<br>#09-01 SINGAPOR  |   |                | Date: | 01/07/2022            |
|   |  |   |                | Code: | AIS                   |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                |       |                       |
|   | Insured Veh.   | SMW 9666U   | Veh. Inspected | l     | SMK 9189T             |
|   | Policy No.   |   | Coverage (\$)  |       | 0.00                  |
|   | Claim No.  | 2022 22004479/SL  | Excess (\$)    |       | 0.00                  |
|   | Assign From  | SHANTI  | Assign Date    |       | 11/04/2022            |
| 2. Vehicle Particulars & Condition                                |  |   |                |       |                       |
|   | Make & Model   | RENAULT SCENIC  | c.c            |       | 1461                  |
|   | Engine No.   | HIDDEN  | Year of Reg.   |       | 2019                  |
|   | Chassis No.  | VF1RFA00362476752   | Colour         |       | WHITE                 |
|   | Odometer   | 174922 KM   | Steering       |       | IN ORDER              |
|   | Brakes   | IN ORDER  | Modification   |       | SPORTS RIM            |
|   | General  | GOOD  |                |       |                       |
| 3. Conditions of Tyres  |  |   |                |       |                       |
|   |  | Size  | Make           |       | Balance               |
|   | R/H Front Tyre   | 195/55 R20  | CONTINENTAL    |       | 6 mm                  |
|   | L/H Front Tyre   | 195/55 R20  | CONTINENTAL    |       | 6 mm                  |
|   | R/H Rear Tyre  | 195/55 R20  | CONTINENTAL    |       | 6 mm                  |
|   | L/H Rear Tyre  | 195/55 R20  | CONTINENTAL    |       | 6 mm                  |
| 4.  | Description of Damages   |   |                |       |                       |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |   |                |       |                       |
|   | DAMAGES SEE DETAILS.   |   |                |       |                       |
| 5.  | General Information  |   |                |       |                       |
|   | Accident Date  | 01/04/2022  | Inspection Dat | е     | 11/04/2022            |
|   | Survey held at   | 1ST AUTOWORKS PTE LTD   | -              |       |                       |
|   |  | 23 KAKI BUKIT AVE 4<br>#04-01 (SOUNTH WING)<br>SINGAPORE 415933 |                |       |                       |
| 5a.   | Remarks  |   |                |       |                       |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                |       |                       |
| 5b.   | Estimate Days of Repair  |   |                |       |                       |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days   |   |                |       |                       |
|   |  |   |                |       |                       |