



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA		Ref: CS/ASM22003308/Avy3e2 Date: 07/09/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGS 1342Z	Veh. Inspected	SMW 6818T
Policy No.		Coverage (\$)	0.00
Claim No.	S2M03Y46	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	11/04/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GP72002951	Colour	BLACK
Odometer	128985 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/55 R16	DUNLOP	6 mm
L/H Front Tyre	185/55 R16	DUNLOP	6 mm
R/H Rear Tyre	185/55 R16	DUNLOP	6 mm
L/H Rear Tyre	185/55 R16	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	06/04/2022	Inspection Date	12/04/2022
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	