

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



		AO I OMOBILE MOI				
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC22003332/Vqy3e2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE Da 189556				06-06-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBK 3991M	Veh. Ir	nspected	SH 7751C	
	Policy No.		Cover	age (\$)	0.00	
	Claim No.	MT/1168041-003	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	11/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI IONIQ	c.c		1580	
	Engine No.	HIDDEN	Year o	f Reg.	2021	
	Chassis No.	KMHC851CVLU193071	Colou	r	BLUE	
	Odometer	133451	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST	_AKE	5 mm	
	L/H Front Tyre	195/65 R15	WEST		5 mm	
	R/H Rear Tyre	195/65 R15	WEST		5 mm	
	L/H Rear Tyre	195/65 R15	WEST	_AKE	5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/04/2022	Inspec	tion Date	11/04/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	ia. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	c. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					