...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUB	FOLDER TRA	CKING								
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subi	mitted	Ins Auth'ed	Status		
Main	11 Apr 2022		11 Apr 2022 17:11 Assign					New Assignment Cancel Case		
CLAIM SUB	FOLDER DET	AILS				[Creat	ted by insurer]			
Insured:		N JUN HAN , ID : S8982208D								
Main	LIM JUN W									
Claimant: Vehicle Reg. No.:	SMD2701	SMD2701Y				: 10/04/2022 19:00 - :59				
Claim Type:	TP / SNM22D202457/C02				olicy/Cover	DMPCSNW00198042100 (Comprehensive)				
Vehicle Reg. No. (Insured):	SMV6621Z	SMV6621Z								
							S\$0.00			
Repairer:	Garage 13	Pte Ltd (HQ) 8 K	aki Bukit Ave 4,	Premier @ Kaki E	Bukit, #03-4	6, 41587	75 Kaki Bukit - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 [Handled by Adeline Chng Pei Wen]									
Adjuster:	LKK Auto C	onsultants Pte L	.td (HO) - Tel: 6	256-3561 [Fi	nal Rot d	ue 21/0	04/20221			
Adj Asg. Remarks:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 [Final Rpt due 21/04/2022] survey revert								
ASSOCIATE	D MAIL RECE	EIVED					Г	View All Compose Case Mai		
There are no	mail for this ca	ise.					-			
ALL ASSOC	CIATED TASK	ς=				View All	Search Tasks	Create New Task Complete		
					_		-			
Due Date No results.	Priority	Type Task 6	iroup Subj	ect Handler	Assign	ed By	Completed (On Created On Done		
No results.										
ALL ASSOC	CIATED FILE	NOTES						Create Nev		
No. Status	Туре		,				Created On Created By By			
No results.		То								
4 D 1110TED!										
	S CLAIM REF		a Theurance (6	Singanoro) Pto	1+4 (HO)					
Assignment F Adj File Ref N		CS3/CTI2200		Singapore) Pte.	signment Da	ato.	11/04/2	n22		
Inspection / Investigation Date:		C55/C112200	3343/13		port Date:		11/04/2	022		
Insurance Cla	aim No:	SNM22D2024		D.c.	cmd'ed Res	/ (S¢)·				
Manager:		VERON CHEN	· · · · · · · · · · · · · · · · · · ·		Recmd'ed Resv. (S\$): Adjuster:					
Clerical:			(First Pick-up)							
	resent Vehicle Loc.: (Check-in: 11/04/2022)									
Assignment R		survey revert	· · · · · · · · · · · · · · · · · · ·							
DESCRIPTI	ON OF VEHIC	CLE								
Vehicle Model		KIA CERATO	1.6 (A)							
Engine No:						Chassis No:				
LTA Reg Date (Man Yr):										
Colour of Vehicle:				Oc	Odometer Reading: - k					
CLAIM LOS	S DETAILS									
Police Report				Pa	rty At Fault:		Unkn	own		
	f Accident/Loss						!			

DOCUMENTS CHECKLIST	All Completed	Reset Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: Handling Insurer			
Note: Remarks are private unless you show it to other parties.			
DOCUMENTS SUMMARY			
Assessment Reports			
Auto Insure Pte Ltd (Toh Guan) [Thumbnails]:(11/04/22) Accident Statement			
Photos/Images			

Documentation

Accident Photo, Accident Photo

China Taining Incurance (Singapore) Dte 1td (HO) [Thumbnailc] (11/04/22) Third Darty E-filed GIA report Pre-Penair Survey

• Auto Insure Pte Ltd (Toh Guan) [Thumbnails]:(11/04/22) Accident Photo, Accid