



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

AXA INSURANCE SINGAPORE PTE LTD

08 April 2022

8 SHENTON WAY
#24-01 AXA TOWER
SINGAPORE 068811

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SND4488M & SH9909C ON 29/03/2022 @ 11:55 HRS ALONG
BLK 630 CARPARK OF BUKIT BATOK CENTRAL

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **SND4488M**

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: **SH9909C**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **SND4488M** and vehicle No.: **SH9909C** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**
160 Sin Ming Drive
#07-01/06 Sin Ming Autocity
Singapore 575722
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SH9909C

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 29/03/2022

TP VEH REG NO : SH9909C

ESTIMATE

NO : QUOT202204-000025(00)

DATE : 08/04/2022

POLICY NO : 999995580

VEH REG NO : SND4488M

MAKE/MODEL : MERCEDES BENZ CLA180
COUPE AMG LINE

CHASSIS NO : W1K1183842N271224

ENGINE NO : 28291480735350

REG. DATE : 2022

Estimate Repair Cost to Vehicle No : SND4488M

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
NET PRICE			
1 Front fender -- LH	1	675.00	675.00
2 Front door - LH	1	1,880.00	1,880.00
3 Front door weatherstrip - LH	1	328.00	328.00
4 Front door trimboard rivets -- LH	20	12.00	240.00
			3,123.00
		Less 10%	312.30
			2,810.70
LABOUR			
5 To transfer LH front damaged door interior mechanism and glass to new door	1	150.00	150.00
6 To panel beat and straighten LH front fender inner panel, LH front door pillar, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
7 To check and rectify wiring system	1	80.00	80.00
8 To putty and spray paint on affected areas	1	1,000.00	1,000.00
			2,230.00
TOTAL			S\$ 5,040.70
ADD GST @ 7%			352.85
GRAND TOTAL			S\$ 5,393.55

SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED NINETY-THREE AND CENTS FIFTY-FIVE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/03/2022 17:13 (SGT)
Date of Accident	29/03/2022 11:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	Bukit Batok central Blk 630
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SND4488M
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Company Reg No	1XXXXXX78Z
Email Address	derrick.lee@daimler.com
Mobile Phone No	(Phone) +65-82821711
Alternative Phone No	(Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	CLA180 COUPE AMG LINE
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1332

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999995580
Cover Note Number	NA

DRIVER

Name of Driver	ER CHEEP HONG (YU ZEHONG)
NRIC No	SXXXX8701



Date Of Birth	28/02/1973
Occupation	Indoor
Date Of Driving Pass	16/04/2001
Driving experience	20 YEARS AND 11 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97481988
Alt. Phone Number	-
Email Address	cheep73@gmail.com
Address	Regent Heights, 56 Bukit Batok East Avenue 5
Address complement	#01-04
Postcode	659804
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

My vehicle SND4488M was parked (stationary) at the open carpark of Blk 630 Bukit Batok Central. While I was stationary, I felt a slight impact coming from the left side of my vehicle and discover that the 3rd party SH9909C front right bumper had a slight scratch onto my vehicle while he was moving out from the parking lot to make a left turn towards the exit, I managed to take some photos and exchange particulars with the 3rd party party. No injuries was involved at the scene.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH9909C
Vehicle Manufacturer	Hyundai
Vehicle Model	Ae ioniq
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	Chia Kwang Fa
NRIC No	SXXXX147F

Contact Number	(Phone) +65-93401213
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

ACCIDENT DIAGRAM Ver. 30042021

A SNO 4488 M
B SH 9909 C



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

REFER TO ATTACHED ACCIDENT DIAGRAM

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle SND4488M was parked (stationary) at the open carpark of Blk 630 Bukit Batok Central. While I was stationary, I felt a slight impact coming from the left side of my vehicle and discover that the 3rd party SH9909C front right bumper had a slight scratch onto my vehicle while he was moving out from the parking lot to make a left turn towards the exit, I managed to take some photos and exchange particulars with the 3rd party party. No injuries was involved at the scene.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

U.S. MARSHALLS REPORT #3

2