

...CLAIM SUBFOLDER...(Pending for Survey Report)

THE REPAIRER HAS NOT SUBMITTED THEIR ESTIMATES

If you wish to work on the report, contact the repairer below to submit it.
You can authorize repairer submission after **5** days.

0.3 days have passed since assignment.
You can authorize the submission of the repairer's estimates in **113 HOURS**.

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Apr 2022 09:30		12 Apr 2022 09:42				Pending for Survey Report Cancel Case

CLAIM SUBFOLDER DETAILS

Insured:	COMFORTDELGRO RENT-A-CAR PTE LTD , Co. Reg. No. : 775H		
Vehicle Reg. No.:	SNB4373X	Date of Loss :	16/03/2022 17:00 - :59 [6 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No. :	D20MFL0000326_01 (Comprehensive)
		Excess:	
Repairer:	ComfortDelGro Engineering Pte Ltd (Braddell) 205 Braddell Road, 579701 Toa Payoh - Tel: 63837613		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 22/04/2022]		
Driver/Custodian:	CHEVALLIER FRANCOIS ROGER ANDRE () Email:		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/Assigned To	Note	Created On	Created By	1st Read By
No results.							

ADJUSTER'S CLAIM REFERENCE

Assignment From:	India International Insurance Pte Ltd (HQ)		
Adj File Ref No:	CS/III22003358/KTY3	Assignment Date:	12/04/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:		Recmd'ed Resv. (S\$):	
Manager:	DENISE TAY KWEE CHENG	Adjuster:	KENNETH KONG
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	ComfortDelGro Engineering Pte Ltd (Braddell) (from est.) (Check-in: 12/04/2022)		

DESCRIPTION OF VEHICLE

Vehicle Model:	KIA CERATO 1.6 EX (A)		
Engine No:	G4FGMH703126	Chassis No:	KNAF3416MM5107423
LTA Reg Date (Man Yr):	23/08/2021 (2021)		
Colour of Vehicle:	Blue	Odometer Reading:	5000 km

CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	

Third Party Involved?	Yes	TP Injury Involved?	Yes (1)
Description of Accident/Loss:			

DOCUMENTS CHECKLIST

All Completed Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Documentation

- **ComfortDelGro Engineering Pte Ltd (Braddell)** [Thumbnails]:(12/04/22) E-filed GIA report, Police Report, Certificate of Insurance
- **India International Insurance Pte Ltd (HQ)** [Thumbnails]:(12/04/22) Singapore Accident Statement