

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2022 Sendback Est	11 Apr 2022 11:23 S\$ 2,662.84	12 Apr 2022 10:13 Edit Adj Rpt				Pending for Survey Report Cancel Case

CLAIM SUBFOLDER DETAILS

Insured:	P D DOOR PTE LTD , Co. Reg. No. : 200412631Z		
Main Claimant:	COMFORT TRANSPORTATION PTE LTE		
Vehicle Reg. No.:	SHA7935G	Date of Loss :	09/04/2022 21:00 - :59 [15 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2201719	Policy/Cover Note No. :	MU012075 (Comprehensive) Coverage: 29/12/2021 - 28/12/2022
Vehicle Reg. No. (Insured):	GBF5930C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Yee Pei Li]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Thevan Thomas Karthikesavan] ... [Final Rpt due 22/04/2022]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/ Assigned To	Note	Created On	Created By	1st Read By
No results.							

ADJUSTER'S CLAIM REFERENCE

Assignment From:	Tokio Marine Insurance Singapore Ltd (HQ)		
Adj File Ref No:	CS/TMI22003362/VQY3	Assignment Date:	12/04/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:	M2201719	Recmd'ed Resv. (S\$):	
Manager:	SHIAU CHAN	Adjuster:	Thevan Thomas Karthikesavan
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	ComfortDelGro Engineering Pte Ltd (Loyang) (from est.) (Check-in: 11/04/2022)		

DESCRIPTION OF VEHICLE

Vehicle Model:	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A)					
Engine No:	ZD30014677N			Chassis No:	JN1SC2F24Z0859142	
LTA Reg Date (Man Yr):	08/01/2021 (2021)					
Colour of Vehicle:	Blue			Odometer Reading:	127116 km	

CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	
Description of Accident/Loss:	ACCIDENT INVOLVING GBF5930C & SHA7935G ALONG BUANGKOK EAST DRIVE		

DOCUMENTS CHECKLIST

All Completed

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Assessment Reports

- ComfortDelGro Engineering Pte Ltd (Loyang) [Thumbnails]:(11/04/22) Repairer Estimates

Documentation

- ComfortDelGro Engineering Pte Ltd (Loyang) [Thumbnails]:(12/04/22) E-filed GIA report