

ASS. REC. BY: Pami

REF:

CC3/AIG22003410/Rqc

9942

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMX 5465Dat Workshop m/s PREMIUMof 24, BENDI SECTIONInsured: AIH

Policy No. _____

Claims No. 9941788663SGSum Insured: _____ Excess: TBA 800

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 166K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMX 5465D Yr Regn: 2021 / JANType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ANDI 3147FS1 S TRONK.C 1395Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 28530 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAW 22ZF33M1060290

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65R17R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FAIRKEN

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 08/04/22 D.O.I. 12/04/22Survey held at 24, BENDI SECTIONDes. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>REPAIR LIMIT - 99K</u>
14/04/22 @ 11.06am	revert to AIG via Merimen.
14/04/22 @ 1.05pm	Kok Chong informed C/A via Merimen.
14/04/22 @ 1.38pm	Informed Jennis C/A & ex:\$800 by email.
21/09/22	Rasul finalised with Mr Boo final fig \$24340 16, 9 days. (Red \$22517.84, 48%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Report Format: MER-OD

Lump Sum / L.B.I. (\$

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0282/2022/NK
DATE : 9-Apr-22
WIP : 19025

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/4/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHIA CHIN SIONG
ADDRESS : 221 UPP PAYA LEBAR RD
#15-02
SINGAPORE 533875
TELEPHONE : HP +65 92318335
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210000310
VEHICLE NO : **SMX 5465 D**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 19/1/2021
ENGINE NO : CZD C22980
CHASSIS NO : WAUZZZF33MI060290
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Apr-22
PLACE OF ACCIDENT : TAMPINES SINGAPORE



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 5465 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WAHSEY ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,700.00 /	
4	TO CARRY OUT PRESSURISE , VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT FENDERS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANIZE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED.	@4.5x5w \$ 5,600.00 2250	
6	TO RESPRAY FRONT BUMPER, BONNET, HINGE AND BOTH FRONT FENDERS.	1pc e3x550+80/80 \$ 4,500.00 1810	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 14,472.00	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 5465 D

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES			REMARKS
		QTY	S/NETT		
1	FRONT BUMPER <i>de /</i>	1	\$	2,146.00	
2	FRONT BUMPER CONNECTING PIECE <i>sur /</i>	1	\$	162.00	
3	FRONT BUMPER CLOSING ELEMENT LH / RH <i>?</i>	2	\$	132.00	
4	FRONT BUMPER CENTRE GRILLE <i>ca /</i>	1	\$	242.00	
5	FRONT BUMPER LOWER COVER <i>?</i>	1	\$	58.00	
6	FRONT BUMPER GRILLE LH / RH <i>?</i>	2	\$	248.00	
7	FRONT BUMPER CLOSING ELEMENT <i>?</i>	1	\$	212.00	
8	FRONT BUMPER SPOILER <i>sur /</i>	1	\$	426.00	
9	AIR GUIDE GRILLE LH / RH <i>?</i>	1	\$	342.00	
10	RADIATOR GRILLE <i>ca /</i>	1	\$	1,594.00	
11	RADIATOR GRILLE STRIKER PLATE <i>ca /</i>	1	\$	271.00	
12	RADIATOR GRILLE CAP COVER <i>?</i>	1	\$	47.00	
13	RADIATOR GRILLE BRACKET <i>?</i>	1	\$	46.00	
14	FRONT CAMERA <i>?</i>	1	\$	1,261.00	
15	FRONT BUMPER FOAM <i>?</i>	1	\$	114.00	
16	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$	974.00	
17	FRONT BUMPER GUIDE SECTION LH / RH <i>?</i>	1	\$	86.00	
18	FRONT BUMPER TOP COVER <i>ca /</i>	1	\$	137.00	
19	SIGN 'CAUTION' STICKER <i>free /</i>	1	\$	16.00	
20	AIR CON STICKER <i>ca /</i>	1	\$	9.00	
SUB TOTAL SPARE PARTS		:	\$	8,523.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 5465 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT SENSOR ?	2	TBC	
22	FRONT SENSOR SEAL RING ?	4	\$ 10.00	
23	FRONT BUMPER WIRING SET ?	1	\$ 750.00	
24	SIGNAL HORN HIGH TONE LH ?	1	\$ 153.00	
25	SIGNAL HORN LOW TONE RH ?	1	\$ 145.00	
26	SPRING SHACKLE LH / RH ?	2	\$ 50.00	
27	BONNET bt/	1	\$ 3,695.00	
28	BONNET HINGE LH / RH bt/	2	\$ 162.00	
29	BONNET ATTACHEMENTS PARTS X	1	\$ 309.00	
30	BONNET STRIKER LH / RH bt/	2	\$ 246.00	
31	SOUND ABSORBER FOR ENGINE BONNET X	1	\$ 244.00	
32	IMPACT PROTECTION CENTRE ok/	1	\$ 31.00	
33	BONNET COVER LH / RH ?	2	\$ 92.00	
34	PLENUM CHAMBER COVER ad/	1	\$ 144.00	
35	BOWDEN CABLE CENTER ?	1	\$ 64.00	
36	BONNET RELEASE LEVER ad/	1	\$ 16.00	
37	BONNET COVER ?	1	\$ 11.00	
38	BONNET LID LOCK CABLE ?	1	\$ 82.00	
39	BONNET RELEASE ELEMENT bt/	1	\$ 65.00	
40	BONNET LID LOCK bt/	2	\$ 455.00	
SUB TOTAL SPARE PARTS		:	\$ 6,724.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 5465 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	WHEEL HOUSING LINER FRONT LH ?	1	\$	260.00	
42	WHEEL HOUSING LINER FRONT RH X	1	\$	260.00	
43	WHEEL HOUSING LINER ATTACHMENTS FRONT/ REAR ?	1	\$	105.00	
44	FRONT FENDER COVER LH / RH X	2	\$	36.00	
45	HEADLIGHT MOUNTING LH / RH	2	\$	264.00	
46	LED HEADLIGHT LH-CM / RH-?	2	\$	11,904.00	
47	LED HEADLIGHT LIFT CYLINDER LH / RH ?	2	\$	462.00	
48	LIFT CYLINDER HOSE RH ?	1	\$	92.00	
49	LOCK CARRIER MOUNTING CM	1	\$	1,412.00	
50	AC CONDENSER ?	1	\$	605.00	
51	COOLANT ?	6	\$	282.00	
52	RADIATOR AIR GUIDE LH / RH ?	2	\$	86.00	
53	RADIATOR AIR GUIDE UPPER / LOWER ?	1	\$	96.00	
54	COVER ?	1	\$	30.00	
55	AIR GUIDE INNER ?	1	\$	59.00	
56	AIR GUIDE OUTER ?	1	\$	21.00	
57	AIR GUIDE CENTRE ?	1	\$	35.00	
58	WHEEL COVER FRONT RH / LH-NE ✓	2	\$	566.00	
59	WATER DEFLECTOR STRIP LH/ RH X	2	\$	104.00	
60	FRONT NO PLATE bt ✓	S/N	\$	60.00	
61	SUNDRIES ?			400	
TOTAL SPARE PARTS			:	\$	32,386.00
TOTAL LABOUR CHARGES			:	\$	14,472.00
GRAND TOTAL			:	\$	46,858.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasul - Hp 90010068
: 12/04/22 @ 1430
: 9 days
: EXCESS: TBA
: Reveal
: Resy before paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/04/2022 10:41 (SGT)
Date of Accident	08/04/2022 07:30 (SGT)
Exact Location of Accident	Tampines, Singapore
Additional Location Information	TAMPINES, SINGAPORE (CARPARK)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX5465D
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHIA CHIN SIONG
NRIC No	SXXXX994Z
Email Address	JAKE.CHIACS@GMAIL.COM
Mobile Phone No	(Phone) +65-9750785
Alternative Phone No	+65-97979322

VEHICLE PARTICULARS

Manufacturer	Audi
Model	Q3
Variant	1.4 TFSI S-TRONIC
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1395

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	7210000310
Cover Note Number	-

DRIVER

Name of Driver	CHIA CHIN SIONG
NRIC No	SXXXX994Z

Date Of Birth	20/07/1985
Occupation	Indoor
Date Of Driving Pass	07/12/2006
Driving experience	15 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-9750785
Alt. Phone Number	+65-97979322
Email Address	JAKE.CHIACS@GMAIL.COM
Address	221 UPPER LEBAR ROAD
Address complement	#15-02
Postcode	533875
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

TURNING OUT OF CARPARK AND ACCIDENTALLY HIT CARPARK WALL.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to a insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Tony Fung

8 April 2022
9:24 am



Describe Circumstances of the Accident

Turning out of carpark and accidentally hit carpark wall.

Declaration

We declare the foregoing particulars are true in every respect.



8 April 2022
9:24 am

Policyholder's Signature / Date &
Time

Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel Tony Fung

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	994Z
Vehicle No.:	SMD5465D
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Apr 2022
Vehicle Make:	AUDI
Vehicle Model:	Q3 1.4 TFSI S TRONIC (177)
Primary Colour:	White
Manufacturing Year:	2020
Engine No.:	CZDC22980
Chassis No.:	WAUZZZF33M1060290
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$27,788.00
Original Registration Date:	19 Jan 2021
First Registration Date:	19 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$30,904.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2031
PARF Rebate Amount:	\$23,178.00
COE Expiry Date:	18 Jan 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,001.00
COE Rebate Amount:	\$42,941.00
Total Rebate Amount:	\$66,119.00

The information contained herein is correct as at 13 Apr 2022

OK

Audi Q3 1.4A TFSI S-Tronic

- [Overview](#)
- [Financial](#)
- [Accessories](#)
- [Similar](#)
- [Research](#)
- [Photos](#)
- [Map](#)

Price	\$168,000		
Depreciation ⓘ	\$17,280 /yr View models with similar depre		Reg Date 09-Feb-2021 (8yrs 9mths 26days COE left)
Mileage	8,000 km (6.8k /yr)	Manufactured ⓘ	2020
Road Tax ⓘ	\$624 /yr	Transmission	Auto
Dereg Value ⓘ	\$64,490 as of today (change)	OMV ⓘ	\$27,785
COE ⓘ	\$46,790	ARF ⓘ	\$30,899
Engine Cap	1,395 cc	Power	110.0 kW (147 bhp)
Curb Weight ⓘ	1,545 kg	No. of Owners ⓘ	1
Type of Vehicle	SUV		

Features

Powered By 1395cc 4 Cylinders Inline 16V Turbocharged Engine, 110.0kW, 147Bhp, 250Nm, 8.9s 0 To 100Km/H.