

ASS. REC. BY: Pam

REF:

C83/11122003426/Rty3

413C

COE XPIR 4:2022/11/11

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLL 8474Hat Workshop m/s HING LEEof 7, woodlands rd 3970 YEW TEE WIL ESTInsured: III

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 6K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLL 8474H Yr Regn: 2007 / MOVType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA WISH 1.8A c.c. 1794Colour: BLUE A/C: Insured / Std / NI / NASp. Reading: 334716 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZNE 100384130Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/55R16R: 71ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 02/04/22 D.O.I. 13/04/22Survey held at HING LEE YEW TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 8 FRNT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 3K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.B. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL



HING LEE MOTOR CAR REPAIR & WELDER WORKS

TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

Pg 1-3

AKW Car Rental.

S L L 8474 H

Date 08/11/22 NO

1.	front bumper. torn /	\$ 804.00	
2	front Head Lamp Assy RH RH-?	\$ 1214.10	
3.	front RH bumper Retainer m /	\$ 171.75	
4.	front RH fender Liner cut /	\$ 371.45	
5.	front RH fender Clip 1 Set m /	\$ 50.00	SN
6	front RH Road. Wheel (Sport) Rim 4 /	\$ 580.00	SN 350 350
7	front RH Tyre ? 70%	\$ 380.00	SN
8	front RH Shock Absorber. ?	\$ 417.90	
9	front RH Lower arm. ?	\$ 422.18	
10	front RH Knuckle ?	\$ 571.10	
11	front RH Knuckle Bearing ?	\$ 230.16	
12	front LH Road wheel (Sport) Rim SC /	\$ 580.00	SN 350
13	front LH Shock Absorber. ?	\$ 417.90	
14.	front LH Lower arm. ?	\$ 422.18	
15.	front LH Knuckle ?	\$ 571.10	
16	front LH Knuckle Bearing ?	\$ 230.16	
17	front LH Tyre ? 70%	\$ 380.00	SN
18	front RH fog Lamp ?	\$ 399.10	
19	1 Set RH Door Wiser m / 120	\$ 150.00	SN
20	Rear RH Door Assy. torn /	\$ 1012.	10
21	Rear RH Dam Regulator. ?	\$ 421.20	
22	Rear RH Door Trim Board. ?	\$ 971.10	

①





HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

SCL 8474 H

Date 08/4/22 NO

23	Rear RH Door glass Outer w/strip m/	\$ 271.74	
24	Rear RH Door w/strip m/	\$ 289.40	
25	Rear RH Door inner Lock. X	\$ 571.10	
26	Rear RH Door Outer handle X	\$ 178.10	
27	Rear RH Door Hinges Lower ?	\$ 177.30	
28	Rear RH Door Hinges Top. X	\$ 187.20	
29	Rear RH Rocker panel. lt/	\$ 688.45	
30	Front RH Door Assy. lt/	\$ 1217.85	
31	Front RH Door inner Lock X	\$ 571.10	
32	Front RH Door w/strip m/	\$ 321.10	
33	Front RH Door glass Outer w/strip m/	\$ 371.75	
34	Little Den pillar RH. repair	\$ 821.22	
35	Front bumper Beam. X	\$ 465.50	
36	Front RH bumper Beam Bracket. X	\$ 172.25	
37	Front bumper Sponge. X	\$ 210.20	
38	Front LH fender Liner. dr/	\$ 371.45	
39	Front LH fender Liner Clip 1 set m/	\$ 50.00	SN



2



興利摩多汽車燒焊廠

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677986
TEL : 762 1010, 763 9909 FAX : 760 2724 Email: hinglee@pacific.net.sg

AKW Car Rental.

SLL 8474 H

Date 08/4/22 NO.

Labour Charge.

1.	front & Rear RH Door Glass Remove & Refit	\$ 120.00	80
2.	winning fee	\$ 50.00	30
3.	Anti Rust	\$ 120.00	80
4.	undercarriage front. Repair & Refit R x L	\$ 400.00	300
5.	wheel alignment	\$ 120.00	80
6.	To Respray Painting Damage Portion	\$ 2000.00	1250
7.	To Repair Acc Damage Portion	\$ 1500.00	1100
8.	Car Seat x interior Remove & Refit	\$ 150.00	80

Cash

Hp 90010068

11 days

L/S

13/04/22 @ 1630

Resurvey after repair



- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/04/2022 14:24 (SGT)
Date of Accident 02/04/2022 00:50 (SGT)
Exact Location of Accident 487 Pasir Ris Drive 4, Block 487, Singapore 510487
Additional Location Information NEAR TO BLK 487 PASIR RIS DR 4 TOWARDS PASIR RIS DR 3
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL8474H

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner AKW CAR RENTAL
Company Reg No 52918413C
Email Address JACKSONANGKS@GMAIL.COM
Mobile Phone No (Phone) +65-94556160
Alternative Phone No (Home) +65-94556160

VEHICLE PARTICULARS

Manufacturer Toyota
Model Wish
Variant -
Exact purpose for which vehicle was being used at time of accident Private hire
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private hire
Transmission Auto
CC 0

INSURANCE COMPANY

Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 5115291903-02
Cover Note Number -

DRIVER

Name of Driver TAN YOKE CHYE
NRIC No S7904486E

Date Of Birth	10/02/1979
Occupation	Outdoor
Date Of Driving Pass	17/12/1999
Driving experience	22 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93393138
Alt. Phone Number	-
Email Address	JACKSONANGKS@GMAIL.COM
Address	APT BLK 406C NORTHSORE DRIVE #13-172
Address complement	-
Postcode	823406
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Merah West Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18003779999
Alt. Police Station Phone No	(Fax) +65-63773923
Police Station Address	500 Bukit Merah View #01-01 Singapore 159682
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM1499C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver
 Contact Number
 Address
 Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1


Name of injured person **TAN YOKE CHYE**
 Gender
 Phone No
 Address
 Address Complement
 Post Code
 Approximate Age Years Old
 Injuries Sustained
 Injured person in which vehicle? **SLL8474H**
 Were seat belts worn? **Yes**
 Was this injured conveyed to hospital by ambulance? **Yes**


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 Policyholder's Signature / Date & Time
 Sketch Plan


 Driver's Signature (if driver is not the policyholder) / Date & Time


 Witnessed by Reporting Centre Personnel



POLICE REPORT ATTACH TO THIS

We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID:	413C
Vehicle No.:	SLLB474H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Apr 2022
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	1ZZ297B992
Chassis No.:	ZNE100384130
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$16,313.00
Original Registration Date:	20 Nov 2007
First Registration Date:	20 Nov 2007
Transfer Count:	4
Actual ARF Paid:	\$17,945.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	19 Nov 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,084.00
COE Rebate Amount:	\$2,968.00
Total Rebate Amount:	\$2,968.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Apr 2022

OK

Toyota Wish 1.8A (COE till 01/2024)

[Overview](#)

[Financial](#)


[Accessories](#)

[Similar](#)

[Research](#)

[Photos](#)

[Map](#)



Price	\$19,800		
Depreciation	\$11,330 /yr	Reg Date	15-Jan-2009 (1yr 8mths 29days COE left)
Mileage	155,000 km (11.7k /yr)	Manufactured	2008
Road Tax	\$1,361 /yr	Transmission	Auto
Dereg Value	\$5,477 as of today (change)	OMV	\$18,803
COE	\$15,668	ARF	\$18,803
Engine Cap	1,794 cc	Power	97.0 kW (130 bhp)
Curb Weight	1,310 kg	No. of Owners	1