

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 63J 3327L

at Workshop m/s Styteck

of

Insured: G3G 6404T

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$120K.

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 4 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: LTA \$18673

Date / Time Action / Instruction Deps 17k.

Veh No: G3J 3327L Yr Regn: 22/03/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / D/CAS

Make: Ford Ranger

C.C. 3198

Colour: Blue

A.O. Insured / Std / NI / NA

Sp. Reading: 47368

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: AFAP XXM J. 2P J572443

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

R: 285/50 R 20

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Re der

Front

Rear

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 09/04/22

D.O.I. 13/4/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: _____

☐

: Site Insp (\$)

) _ \$ + RS _ \$

☐

: Interview (\$)

) Photos

☐

: Tech. Invs (\$)

) Others

☐

: Weekend (\$)

)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

20/4/22 2/5 \$5800 informed Winston.

Vehicle: GBJ3327L

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed as it is subject to final approval from the survey company

Make & Model:

FORD RANGER

Acknowledged by Repairer

Chassis No:

AFAPXXMJ2PJS72443

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Tailgate		1900.00	\$ 1,988.30	20/30t ✓
2	Rear Tailgate "70km/h" Sticker			\$ 15.00 SN	new 10 S/N
3	Rear Tailgate "Emblem"			\$ 320.40	17X
4	Rear Tailgate "LIMITED" Wording			\$ 120.80	121 ✓
5	Rear Tailgate "RANGER" Sticker			\$ 360.50	121 ✓
6	Rear Tailgate Inner Garnish			\$ 650.80	17X
7	Rear Tailgate Inner Garnish Rubber			\$ 208.60	17X
8	Left Taillamp		600.00	\$ 786.40	CNA ✓
9	Left Taillamp Moulding			\$ 186.40	CN7 ✓
10	Rear Bumper (Chrome) Left & Right	820x72=1640 2	960.6	\$ 1,921.20	D.O ✓
11	Rear Bumper Step Garnish	1100		\$ 1,321.60	D.O ✓
12	Rear Bumper Lower Garnish			\$ 380.40	CN7 ✓
13	Rear Bumper Reverse Sencer			\$ 350.00 SN	shhd ✓ 250 S/N
14	Rear Bumper Inner Support	820		\$ 1,350.40	But ✓
15	Left Rear Fender "4X4" Sticker	100		\$ 190.20	121 ✓
16					202
Labour					
1	Check Wiring			\$ 100.00	-20
2	Anti Rust Proof			\$ 100.00	40
3	Panel Beating			\$ 800.00	500
4	Paint Work			\$ 1,000.00	700

STYTECH AUTO PTE. LTD.
 2 Kaki Bukit Ave 2 #01-03
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

not return
 2/5 \$5800
 13/4/22
 4 days
 1/2

P-7238-1
 202
 5790.48
 260
 1860