



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                        |                                                                                                                                        |                                                                          |                          |            |
|----------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|--------------------------|------------|
| TOKIO MARINE INSURANCE SINGAPORE LTD<br>20 MCCALLUM STREET #09-01<br>TOKIO MARINE CENTRESINGAPORE 069046 |                                                                                                                                        |                                                                          | Ref: CS/TMI22003443/Vty3 |            |
|                                                                                                          |                                                                                                                                        |                                                                          | Date: 14/04/2022         |            |
|                                                                                                          |                                                                                                                                        |                                                                          | Code: TMI                |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                        |                                                                                                                                        |                                                                          |                          |            |
|                                                                                                          | Insured Veh.                                                                                                                           | SLM 7149Z                                                                | Veh. Inspected           | SHB 6234Y  |
|                                                                                                          | Policy No.                                                                                                                             | MN000206                                                                 | Coverage (\$)            | 0.00       |
|                                                                                                          | Claim No.                                                                                                                              |                                                                          | Excess (\$)              | 0.00       |
|                                                                                                          | Assign From                                                                                                                            | Telma Gomez                                                              | Assign Date              | 14/04/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                            |                                                                                                                                        |                                                                          |                          |            |
|                                                                                                          | Make & Model                                                                                                                           |                                                                          | c.c                      | 0          |
|                                                                                                          | Engine No.                                                                                                                             | HIDDEN                                                                   | Year of Reg.             |            |
|                                                                                                          | Chassis No.                                                                                                                            |                                                                          | Colour                   |            |
|                                                                                                          | Odometer                                                                                                                               | -                                                                        | Steering                 |            |
|                                                                                                          | Brakes                                                                                                                                 |                                                                          | Modification             |            |
|                                                                                                          | General                                                                                                                                |                                                                          |                          |            |
| <b>3. Conditions of Tyres</b>                                                                            |                                                                                                                                        |                                                                          |                          |            |
|                                                                                                          |                                                                                                                                        | Size                                                                     | Make                     | Balance    |
|                                                                                                          | R/H Front Tyre                                                                                                                         |                                                                          |                          | mm         |
|                                                                                                          | L/H Front Tyre                                                                                                                         |                                                                          |                          | mm         |
|                                                                                                          | R/H Rear Tyre                                                                                                                          |                                                                          |                          | mm         |
|                                                                                                          | L/H Rear Tyre                                                                                                                          |                                                                          |                          | mm         |
| <b>4. Description of Damages</b>                                                                         |                                                                                                                                        |                                                                          |                          |            |
|                                                                                                          |                                                                                                                                        |                                                                          |                          |            |
| <b>5. General Information</b>                                                                            |                                                                                                                                        |                                                                          |                          |            |
|                                                                                                          | Accident Date                                                                                                                          | 13/04/2022                                                               | Inspection Date          | 14/04/2022 |
|                                                                                                          | Survey held at                                                                                                                         | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                          |            |
| <b>5a. Remarks</b>                                                                                       |                                                                                                                                        |                                                                          |                          |            |
|                                                                                                          | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                          |                          |            |