



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS/ASM22003456/Uqy3e2 Date: 10/05/2022 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	EM 1881P	Veh. Inspected	SFG 6996D
	Policy No.		Coverage (\$)	0.00
	Claim No.	S2M03YK2	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	14/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	B.M.W. 520I (A)	c.c	1997
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WBAXG12020D291300	Colour	GREY
	Odometer	157451 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/45 R18	PIRELLI	6 mm
	L/H Front Tyre	215/45 R18	PIRELLI	6 mm
	R/H Rear Tyre	245/45 R18	PIRELLI	6 mm
	L/H Rear Tyre	245/45 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	12/04/2022	Inspection Date	22/04/2022
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	