

ASS. REC. BY:

REF:

CS/EGI22003458/Dgy<sup>3</sup>

## ASSIGNMENT

DE Dec 2027

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SH 6616 S Yr Regn: Dec / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai Ioniq c.c 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: H.A. T/Radio: Insured / Std / NI / NA

Eng/No: G4LEKU408490

C/No: KMHC851CVLU189771

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 09/04/2022 D.O.I. 18/04/2022

Survey held at Biprost sin Mine

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Bigo TP 9045 G
	Vehicle balance 68 mths. Mett value calculation done behind.
31/10/22	Pay 1/5 33,000 - with 16 days go (led to 29/13.16, 4377)

Date/Time, File Pass to?

1) 02/11/2022

Date/Time, File Return to?

2)

☐: Preli. Report☐: Final Report

Days Of Repair: 16

Resurvey No. of Trip: 2

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech. Invs (\$)☐: Weekend (\$)

Survey Fee:

Transportation:

S+RS SI

Photos

Others

TOTAL

Report Format: WERTP

Lump Sum / I.B.I. (\$) 33000



# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

18/04/2022 @ 1400hrs

Not Author

1 year 16 days

2cc Auto

Check part prices  
Provide Bv before  
any work

DATE: 18-Apr-22

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 6616S

Description	Qty	List Price	Amount
Bonnet <i>Double</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Hinge (LH/RH) <i>vt</i>	2	\$ 118.70	\$ 237.40
Bonnet Moulding <i>MF</i>	1	\$ 41.40	\$ 41.40
Bonnet Lock <i>vt</i>	1	\$ 127.30	\$ 127.30
Bonnet Insulator <i>HN</i>	1	\$ 230.10	\$ 230.10
Bonnet Insulator Clips <i>HN</i>	1	\$ 15.00	\$ 15.00
Radiator Grille NEW MODEL <i>broken</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH/RH) <i>broken</i>	2	\$ 824.60	\$ 1,649.20
Speaker Assy-VESS <i>broken</i>	1	\$ 554.40	\$ 554.40
Flap Assy Active wire <i>socket broken</i>	1	\$ 765.30	\$ 765.30
Front Number Plate garnish <i>Double</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>horn</i>	1	\$ 481.10	\$ 481.10
Front bumper top cover <i>broken</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>horn</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>Double</i>	1	\$ 1,136.70	\$ 1,136.70
Front Bumper Reinforcement ABSORBER (LH/RH) <i>vt</i> <i>Double</i>	2	\$ 186.50	\$ 373.00
Front Bumper Towing Cover <i>dislodged</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>cut</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>MF</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffener <i>vt</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>broken</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>cut</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>HN</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>o/s HN 4/5 broken</i>	2	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>broken H/S o/s HN</i>	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH/RH) <i>HN</i>	2	\$ 65.30	\$ 130.60
Front Bumper Clips 10 pcs <i>Hec</i>	1	\$ 25.00	\$ 25.00
Front Bumper Grille (LH) <i>dislodged</i>	1	\$ 186.90	\$ 186.90
Front bumper air duct (LH) <i>HN</i>	1	\$ 153.80	\$ 153.80
Day Light, LH <i>mounty broken</i>	1	\$ 642.50	\$ 642.50
Day Light Wire, <i>HN</i>	1	\$ 585.50	\$ 585.50
BUZZER ASSY - PIEZO (LH) <i>HN</i>	1	\$ 388.00	\$ 388.00
Headlamp Support Panel Assy <i>broken</i>	1	\$ 1,139.30	\$ 1,139.30
Headlamp(LH/RH) <i>broken</i> <i>2110.30 x 2</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>broken</i>	2	\$ 72.80	\$ 145.60
Horn Wire <i>horn</i>	1	\$ 386.70	\$ 386.70
Radiator Inverter <i>vt</i> <i>punctured</i>	1	\$ 884.80	\$ 884.80
Radiator <i>vt</i> <i>punctured</i>	1	\$ 710.50	\$ 710.50
Radiator fan blower motor assy <i>broken</i>	1	\$ 1,459.60	\$ 1,459.60
Radiator Air Guard (LH/RH) <i>src</i>	2	\$ 76.40	\$ 152.80
Radiator Air Guard, Upr (LH/RH) <i>src</i>	2	\$ 127.50	\$ 255.00
Front Fender(LH/RH) <i>Double</i>	2	\$ 490.70	\$ 981.40

4220.60

22,019.40



Front Fender Shield (LH/RH) o/s HH H/s torn   broken	2	\$ 164.70	\$ 329.40	✓
Aircon Condenser <del>not</del> punched	1	\$ 663.60	\$ 663.60	✓
Aircon Suction & Liquid Hose HH	1	\$ 679.60	\$ 679.60	X 17,588.20
Frt Safety Belt(Assy)(LH/RH) <del>actuated</del>	2	\$ 648.90	\$ 1,297.80	✓
Rear Safety Belt(Assy)(LH/RH) <del>actuated</del>	2	\$ 513.20	\$ 1,026.40	✓
Rear Safety Belt Garnish Cover(LH/RH) broken   missing	2	\$ 398.00	\$ 796.00	✓
Front Windscreen Glass <del>Weld</del> <del>delivered</del>	1	\$ 1,558.10	\$ 1,558.10	✓
Front Windscreen Moulding H/C	1	\$ 157.30	\$ 157.30	✓
electronic clutch actuator assy broken	1	\$ 6,345.80	\$ 6,345.80	✓ 4836.50
Dashboard Complete broken	1	\$ 4,724.00	\$ 4,724.00	✓ 1474.00
Passenger Air Bag <del>actuated</del>	1	\$ 2,633.00	\$ 2,633.00	✓ 1951.20
Steering Airbag Complete <del>actuated</del>	1	\$ 1,090.90	\$ 1,090.90	✓
Airbag Control Module <del>actuated</del>	1	\$ 1,243.70	\$ 1,243.70	✓
Knee control airbag module assy <del>actuated</del>	1	\$ 578.60	\$ 578.60	✓
Steering Angle Assy HH	1	\$ 786.90	\$ 786.90	X
Sensor Assy Impact -Frt Impact HH	1	\$ 643.90	\$ 643.90	X
Airbag Sensor (LH/RH) <del>actuated</del>	2	\$ 348.10	\$ 696.20	✓
SUB TOTAL			\$ 53,168.50	39,607.60
LESS 20%			\$ 10,633.70	31,686.08
DISCOUNTED TOTAL			\$ 42,534.80	
Front Number Plate <del>dislodged</del> SN	1	\$ 25.00	\$ 25.00	} 45/-
Front No Plate Trim Cover <del>dislodged</del> SN	1	\$ 30.00	\$ 30.00	
COOLANT HH SN	1	\$ 45.00	\$ 45.00	X
Inverter COOLANT HH SN	1	\$ 65.00	\$ 65.00	X
Emblem-Blue Drive (LH/RH) H/C List SN	2	\$ 26.60	\$ 53.20	✓ List
Front Windscreen Sealant H/C SN	1	\$ 46.00	\$ 46.00	✓
Front ERP Bracket H/C SN	1	\$ 30.00	\$ 30.00	✓
Clutch Fluid HH SN	2	\$ 85.00	\$ 170.00	X 121.00/-
SUB TOTAL			\$ 464.20	
<b>Labour Charge</b>				
Panel Beating	1	\$2,000.00	\$2,000.00	1300/-
Spray Painting Charge	1	\$1,600.00	\$1,600.00	900/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$100.00	\$100.00	40/-
Towing Charge	1	\$80.00	\$80.00	HH
Four Wheel Alignment	1	\$120.00	\$120.00	HH
Remove/Refix Undercarriage (Frt)	1	\$400.00	\$400.00	HH
Re-set Frt ABS System	1	\$200.00	\$200.00	HH
Remove/Refix Radiator	1	\$90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box	1	\$120.00	\$120.00	50/-
Remove/Refix Front Windscreen Glass	1	\$120.00	\$120.00	80/-
Remove/Refix Engine	1	\$600.00	\$600.00	HH
Remove/Refix Dashboard	1	\$350.00	\$350.00	150/-
Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat	1	\$550.00	\$550.00	} 180/-
Re-programme Air Bag & Safety Belt System	1	\$550.00	\$550.00	
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	
TOTAL LABOUR			\$7,660.00	
ESTIMATE TOTAL			\$ 50,659.00	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance				



# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 19-Apr-22

INSURANCE: Ergo

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 6616S

Description	Qty	List Price	Amount
Front Fender Apron Panel (LH/RH) <i>key</i>	1	\$ 756.20	\$ 756.20
Air Cleaner Hoauing Assy <i>broken</i>	1	\$ 1,636.50	\$ 1,636.50
Wiring-Engine <i>broken</i>	1	\$ 6,675.00	\$ 6,675.00
SUB TOTAL			\$ 9,067.70
LESS 20%			\$ 1,813.54
DISCOUNTED TOTAL			\$ 7,254.16
ESTIMATE TOTAL			\$ 7,254.16

X  
✓  
✓

8311.50  
6,649.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

*1 ryan*

2kk Ando

*[Signature]*

34,667.08  
supp 6,649.20  
41,316.28  
L/S 33,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SH6616S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	13 Apr 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU408490
Chassis No.:	KMHC851CVLU189771
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,344.00
Original Registration Date:	19 Dec 2019
First Registration Date:	19 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$12,482.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2027
PARF Rebate Amount:	\$9,361.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,581.00
COE Rebate Amount:	\$18,162.00
<b>Total Rebate Amount:</b>	<b>\$27,523.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 13 Apr 2022

OK



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	11/04/2022 18:50 (SGT)
Date of Accident	09/04/2022 05:50 (SGT)
Exact Location of Accident	Sims Ave E, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SH6616S

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-98165499
Alternative Phone No	(Office) +65-65508768

### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

### DRIVER

Name of Driver	LEONG KHAI WENG
NRIC No	SXXXX048C

Date Of Birth	10/09/1960
Occupation	Outdoor
Date Of Driving Pass	19/06/1985
Driving experience	36 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98165499
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	BLK 81 BEDOK NORTH ROAD #09-302
Address complement	-
Postcode	460081
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Cross Junction
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

REPORT NUMBER: T/20220409/7028

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-







Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

### INJURED PERSONS DETAILS

#### INJURED 1

Name of injured person	LEONG KHAI WENG
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	FEEL PAIN ON HAND AND NECK AND UPPERBACK AREA
Injured person in which vehicle?	SH6616S
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :


- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 17:05 11.04.22

Witnessed by Reporting Centre Personnel MD NA2RIN



A - SH6616S  
B - UNKNOWN







Describe Circumstances of the Accident

REPORT NUMBER: T/20220409/7028

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

7 / 9

Driver's Signature (If driver is not the policyholder) / Date  
& Time 17:05 11.04.22

Witnessed by Reporting Centre  
Personnel MONA P. IN



# SINGAPORE POLICE FORCE



T/20220409/7028

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20220409/7028

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 09/04/2022 17:31		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: LEONG KHAI WENG			Address: 81 BEDOK NORTH ROAD #09-302 SINGAPORE 460081		
ID Type / ID No.: NRIC NO / S1412048C			Contact No.: Home/Office: Mobile: 98165499		
Nationality: SINGAPORE CITIZEN			Email: LAWRENCE_LEONG@LIVE.COM.SG		
Sex: Male	Age: 61	Date of Birth: 10/09/1960	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 09/04/2022 05:50	Type of Location: X-Junction
Location:  SIMS AVENUE EAST				
Weather: Raining		Road Surface: Wet	Road Speed Limit: 50 Km/h	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SH6616S	Car					0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





**SINGAPORE  
POLICE FORCE**



T/20220409/7028

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20220409/7028

**CONTINUATION OF REPORT**

<b>Driver</b>				
Name	LEONG KHAI WENG		ID No.	S1412048C
Related Vehicle	SH6616S (Car)		Contact No.	98165499
Hospital/Clinic	CHANGI GENERAL HOSPITAL		Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	09/04/2022		Date	09/04/2022
No. of Days granted Medical Leave	05	Degree of	Slight	

**Brief Details.**

On the morning of 9th April 2022 about 0550 hrs I was driving my taxi SH6616S along Sims Avenue East towards Bedok. Approaching the junction the traffic light was green so I proceed on but suddenly a lorry appeared travelling from left to right and did not stop. I instantly reacted by jamming my brakes and I can feel the ABS reacting and my taxi skidded slightly before colliding into the side of the lorry. The airbags activated and my seat belt prevented me from going forward. I felt pain on my right hand and neck and upper back area. There were smoke coming out of the engine and driver compartment so I opened the windows only slightly as it was raining. I managed to find my handphone and call police emergency for traffic police and ambulance. I tried to open the door but it was jam but I managed to push it open for me to squeeze out of the taxi. I was alone with no passengers. I saw the driver of the lorry and ask him why he did not stop when his lights was red. He replied that it was raining and will skidded if he braked. The medical services arrived and I was attended to and the police arrived. It was raining moderately and the traffic was light.





**SINGAPORE  
POLICE FORCE**



T/20220409/7028

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20220409/7028

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
MUHAMMAD ISMAIL BIN AMZAH  
Contact No.: 65476185

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
09/04/2022 17:31

Classification Of Case:



SH 6616S

Book Value

$$\text{Total Purchase Cost} = 73,231.63$$

$$\text{Less PRRF } 7489.20 = 65,742.43 / 96$$

$$\text{Depr / mtr} = 684.81 \times 68$$

$$\text{Remaining life span } 68 \text{ mtr} = 46,567.08$$

$$\text{Add PRRF } 7489.20 = 54,056.28$$

~~Cost~~ Value

$$\text{Less LTA value } 27,523.00 = 54,056.28 - 27,523.00$$

$$= 26,533.28 \text{ net value}$$