

Your Ref : **SGL 2882L**
Our Ref : **JP/DS/22/SJF 9190A/SHMS**
Date : **14 April 2022**

Fax : **6538 3708**
Tel : **3152 0985**
Email : **jiapei@kscgp.com**

AXA INSURANCE SINGAPORE PTE LTD

BY EMAIL ONLY

DATE OF ACCIDENT: 13 APRIL 2022

NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY / INSPECTIONS

We refer to your email of even date.

Please be informed that our client is not agreeable to your proposed motor surveyors. Instead we propose you to choose a surveyor from our client's list of surveyors as appended below:-

| S/No. | Name of Surveyor | Company Name |
|-------|------------------|----------------------------|
| 1. | Lek Boon Hwee | Auto Performance Appraisal |
| 2. | Oh Han Cheong | Oh Appraisal Services |
| 3. | Lim Say Koon | SK Appraisal Pte Ltd |
| 4. | Edwin Koh | Auto Hyperdeals Pte Ltd |

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors. You will be deemed to have agreed to any of the above motor surveyors as a "single joint expert". We will inform you who the "single joint expert" is in due course.

If you object to our client's list of motor surveyors, we will accordingly inform the client to instruct his choice of motor surveyor to conduct the pre-repair survey. Also, please let us know within 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle failing which our client will commence repairs thereafter without any further notice or reference to you. Please be informed that the said vehicle can be surveyed / inspected at:

Address : Sau Hock Motor Services
Blk 10 Ang Mo Kio Industrial Park 2A (Avenue 5)
#02-14 Ang Mo Kio Autopoint
Singapore 568047

Contact Person/Tel : Mr Robert Tan
Mb : 91098638

Yours faithfully,

DS

Your Ref : **SGL 2882L**
Our Ref : **JP/DS/22/SJF 9190A/SHMS**
Date :

Acknowledgement

This is to confirm that I _____ *[Full Name of Surveyor]* of _____ *[Surveyor's Company]* have completed as follows:-

(a) Pre- Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(b) Pre- Repair Survey/Inspection (during dismantling) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(c) Re-inspection of new replacement part (part by part) on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date:

(d) Post – Repair Survey/Inspection on _____ [Date] at _____ [Time].

Name and signature of Appointed Surveyor
Company Stamp

Witnessed by:
Date: