



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003469/Kqy3n2 Date: 03/06/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJH 1814B	Veh. Inspected	SLH 1066U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014647/KY	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	14/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI ATTRAGE (A)	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH003176	Colour	METALLIC RED	
Odometer	34607 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	YOKOHAMA	8 mm	
L/H Front Tyre	185/55 R15	YOKOHAMA	8 mm	
R/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/55 R15	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/04/2022	Inspection Date	05/05/2022	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD (HQ) 176 SIN MING DRIVE #01-06/07/13, SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	