ASS. Filed By: GQ | REF: CS/AIS22003474/Gvy3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / W/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s TAN CHONG MOTOR

of

Insured: XD 8367J

Policy No.

Claims No. 800SWAISSCL20220083SL-XD8367J

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: $62k

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMF9229M Yr Regn: 18 Dec/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: NISSAN / NOTE 1.2 c.c 1198

Colour Brown A/C: Insured / Std / NI / NA

Sp.Reading 30102 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1TAAE12Z0982419

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CONTINENTAL

Front		Rear	
R/Bal.	8 mm	R/Bal.	8 mm
L/Bal.	8 mm	L/Bal.	8 mm

D.O.A. 12/4/2022 D.O.I. 18-04-2022

Survey held at W/S 10AM

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
4/5/22	Final fig $2244 (red 584.72, 21%)

Date/Time, File Pass to? 1)

Date/Time, File Return to? 2) 4/5/22-typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other

TOTAL

Report Format: TP

Lump Sum / IBI: $2244