## SKETCH PLAN

## ANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
  of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

A: Sky 4907L

B: SFN 5955 A (ME)

C: SLQ 8936 R

Driver's Signature (If driver is not the policyholder) / Date Reporting Centre Personnel

Time

C: SLQ 8936 R

D: SJH 8714 K

D: SJH 8714 K

Describe Circumstances of the Accident
On 13 Apr 2002 @ 0800 HC, I was driving STO 5958A along PIE toward
ECP (Fly over). The Car infront Sku49072 Stop and I stop the car SFU 5955A. Both the cars are stationary. The car behind me sign 936R barg into my car and put or push my car forward. Although my car brake is still apply, the car behind me push my car forward, and hit the front car. My front and back are damaged. Some particulars are exchange and took some photo.  After article auchle TP front and only law, arrived at from
SFU 59557. Both the rars are stationary. The rar behind me SLQ8936R
bang into my car and put in push my car forward. Although my
car brake is still apply, the car behind me push my car forward.
and hit the frost car- my front and back are damaged.
Some particulars are exchange and took some photo.
After a strye autile, TP, Errors and ambulance arrived at Scene.
TP dis ask me and front car to go as our care are mobile and
on one was injured at that time.
That all.
3
Air bag warning light appear after the accident.
the design.

## Declaration

IWe declare the foregoing particulars are true in every respect.

RENREY & 13 Apr 2022

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel