



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003503/Kny3e2 Date: 05/07/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMH 3520A	Veh. Inspected	SKN 9204R	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014760/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	18/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF TSI (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WVWZZZAUZFW006514	Colour	METALLIC GREY	
Odometer	61877 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R17	MICHELIN	6 mm	
L/H Front Tyre	225/45Z R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45Z R17	MICHELIN	4 mm	
L/H Rear Tyre	225/45Z R17	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2022	Inspection Date	18/05/2022	
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		