



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO22001601/Uvy3e2-1	
			Date: 06/05/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 6194P	Veh. Inspected	GBL 4280U	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2200282/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 VANETTE DX (A)	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	VM20165907	Colour	WHITE	
Odometer	12068 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	165/80 R14	TOYO	6 mm	
L/H Front Tyre	165/80 R14	TOYO	6 mm	
R/H Rear Tyre	165/80 R14	TOYO	6 mm	
L/H Rear Tyre	165/80 R14	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/01/2022	Inspection Date	21/02/2022	
Survey held at	A S AUTO SERVICE NO 1 KAKI BUKIT #01-106 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	