

REF: CS1/LPM22001222/Kty3

Special Instruction:

From (Person): LILLIAN SIM of LPM ASSIGNMENT (Office) Date/Time: 18/04/2022
Estimated Cost: _____ Bill to: _____

LS : \$9000 / 5 DAYS

Third Parties:

Claimant:

Surveyor: PRESTIGE APPRAISER

Workshop: YEE AUTO PTE LTD

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJT 3353M Insured: WUD 2693
at Workshop m/s YEE AUTO PTE LTD Tel: _____
of 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722

Policy No: _____ Claim No: 19/19/20/VP02/300374

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18/09/2019
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 6/5/2022 Confirmed with Final Fig , days (Red \$ / %; Original 7 days)

Date/Time: 6/5/2022 Submit Final Fig 2500, 4 days (Red \$ 6500 / 72 %; Original 5 days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

Date/Time		File Pass to		File Return to		Total
1)	Date/Time		File Pass to	2)	Date/Time	File Return to
3)	Date/Time		File Pass to	4)	Date/Time	File Return to
5)	Date/Time		File Pass to	6)	Date/Time	File Return to