



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003570/Dny3e2	
			Date: 23/08/2022	
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLB 1486Y	Veh. Inspected	SLK 6841A
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10014762/CD	Excess (\$)	0.00
	Assign From	SHAFAWATI MD RABU	Assign Date	19/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF 1.4 TSI	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WVWZZZAUZHW069750	Colour	WHITE
	Odometer	95957 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35 R19	MICHELIN	5 mm
	L/H Front Tyre	235/35 R19	MICHELIN	5 mm
	R/H Rear Tyre	235/35 R19	MICHELIN	5 mm
	L/H Rear Tyre	235/35 R19	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/04/2022	Inspection Date	20/04/2022
	Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	