



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22003575/Aqy3e2	
			Date: 13/05/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBG 9730G	Veh. Inspected	SBS 3087G
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2201175/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	19/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	VOLVO B9TL	c.c	9364
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	YV3S4P923CA154227	Colour	WHITE
	Odometer	866236 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm
	L/H Front Tyre	275/70 R22.5	BRIDGESTONE	6 mm
	R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm
	L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	6/6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	06/04/2022	Inspection Date	19/04/2022
	Survey held at	SBS TRANSIT LTD (Branch) BUKIT BATOK ST 23 SINGAPORE 659519		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	