

PRS

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD TP / S / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s 3 Motorwerkz Concept
 of _____
 Insured: SJW 3324G
 Policy No: _____
 Claims No. S2M03YRR
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SGK8350X Yr Regn: 28 Aug 2006
 Type M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA LEXUS GS300 c.c 2995
 Colour Black A/C: Insured / Std / NI / NA
 Sp.Reading 235041 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTHBG96S505043803 *
 Gen. Cond Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/R / m or
 Tyre Size: F: 255/35ZR19
 R: //

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$35k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 10 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front		Rear	
R/Bal. 6	mm	R/Bal. 6	mm
L/Bal. 6	mm	L/Bal. 6	mm
D.O.A. 18/4/2022		D.O.I. 19-04-2022	
Survey held at	W/S	5:30PM	

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$8000 - \$10000
21/4/22	Submit PRS, repair range \$8,000-\$10,000

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 10
 Resurvey No. of Trip: _____

1) _____
 Date/Time, File Return to?
 2) 21/4/22-typist
 Report Filed?
 Long Copy/MP/...

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Insp (\$ _____)
 : W/weekend (\$ _____)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	