

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD	F	Ref:	CS/INC22003602/Kny3m4
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Г	Date:	04/08/2022
	ATTN: JEFF LIN		(Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGT 4818T	Veh. Inspected		FBS 2114T
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1168970-001	Excess (\$)		0.00
	Assign From	ANNIE KOH	Assign Date		19/04/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FORZA NSS300A (A)	c.c		279
	Engine No.	HIDDEN	Year of Reg.		2021
	Chassis No.	MLHNF0795J5000764	Colour		METALLIC SILVER
	Odometer	21350 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/70 R15	PIRELLI		6 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	140/70 R14	PIRELLI		7 mm
	L/H Rear Tyre				mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DE	= I AILS.			1
5.	General Information				
	Accident Date	16/04/2022	Inspect Date / Ti	ime	19/04/2022 (11:15 AM)
	Survey held at	SG 98 MOTOR PTE LTD			
		BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
5b.	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. Estimate Days of Repair				
35.	ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				
			<u> </u>		9,-