

Ass. Rec. By:

REF:

CS/INC22003603/Any3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1168910-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLS6473L Yr Regn: 2017, Sept

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astra C.C. 999

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 148148 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOLBE6EAOH6174537

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/45R17.

R: 225/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Glade.

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 19/04/22.

Survey held at Xin Hua.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP INC.

Adrian confirmed lump sum: \$7400 and 8 days

MV: (red, 30111.53, 80%)

PV:

Nett:

216Z

Date/Time, File Pass to?

☐

Preli. Report

1) 17/11/22

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)

Survey Fee:

Transportation:

S + RS \$

Phone

Others

Report Format: 7400

Insurance Company / P.P. / P.P.

CITY TYREAUTO PTE LTD
219 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416044

TEL: 67466686

H/P: 85153676

Work Order: R004643
License: SLS6473L
Date: 14.4.22 17:45

Opel : Astra : 2012-18 (Astra-J) : 4 Door / 5 Door : Standard Suspension

Front : Left

Actual	Before	Specified Range
-0°50'	-0°50'	-1°06' 0°24'
4°27'	4°27'	3°42' 5°12'
0°08'	0°08'	-0°04' 0°08'
1°20'	1°20'	
0°30'	0°30'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°35'	-0°35'	-1°06' 0°24'
4°27'	4°27'	3°42' 5°12'
0°11'	0°11'	-0°04' 0°08'
1°05'	1°05'	
0°30'	0°30'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°15'	-0°15'	-0°45' 0°45'
0°00'	0°00'	-0°45' 0°45'
0°15'	0°15'	
0°19'	0°19'	-0°07' 0°17'

Rear : Left

Actual	Before	Specified Range
-1°25'	-1°25'	-1°54' -0°54'
0°14'	0°14'	-0°09' 0°15'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
1°54'	1°54'	-1°54' -0°54'
1°09'	1°09'	-0°09' 0°15'

Rear

Cross Camber
Total Toe
Cross Toe
Thrust Angle

Actual	Before	Specified Range
-3°19'	-3°19'	-0°36' 0°36'
1°23'	1°23'	-0°18' 0°30'
-0°55'	-0°55'	-0°36' 0°36'
-0°28'	-0°28'	-0°18' 0°18'