



Company & GST Registration No. 200616038C

2 Kaki Bukit Avenue 2 #01-17/#01-18 /Heavy Vehicle #01-08/Spray Painting #02-27

Kaki Bukit Autohub Singapore 417921

Tel: 68420051

Fax: 67410510

Email: sales@n51.com.sg

Our Ref:

SMA 5772 M

Your ref:

SMK 6995 C

19 April 2022

AUTO & GENERAL INSURANCE (S) PTE LTD

SINGAPORE SHOPPING CENTRE

190 CLEMENCEAU AVENUE #03-01

SINGAPORE 239924

Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : TWINCAR LEASING PTE LTD

VEHICLE NUMBER : SMA 5772 M

YOUR INSURED VEHICLE NUMBER : SMK 6995 C

ACCIDENT ON 16 Apr 2022 ALONG TANGLIN RD JUNC KAY SIANG RD

AT ABOUT 16:30 HOURS

We refer to your email/fax dated **19 Apr 2022** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-18

Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

N-51 AUTOMOTIVE PTE LTD