COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

LKK-

DATE:

MODEL:

18.04.22

Hyundai i40

VEHICLE NO .: SH 8352P

INSURANCE: NTUC -45

MVA: LIM TS

Pront Bumper / 22				
Front Bumper / DE				
	1		\$ 1,052.20	
- 14	10	\$ 2.20	\$ 22.00	
Front Bumper Side Bracket I H	1		\$ 22.40	
Front Fender LH / Buc	1		\$ 663.00	
Front Fender Shield LH	1		\$ 174.90	
Front Fender Retainer LH	1			
HeadLamp LH X	1		\$ 1,388.00	
Front Wheel Cap LH	1			
Front Wheel Rim LH	1		\$ 325.60	
SUB TOTAL			\$ 4,082.50	2454.9
			\$ 816.50	
DISCOUNTED TOTAL			\$ 3,266.00	1963.92
Front Wheel Tyre LH / Gal	1		\$ 216.00	Nett 129.6
SPARE PARTS TOTAL			\$ 3,482.00	
Labour Charge				101
Panel Beating			\$ 800.00	200
Spray Painting Charge			\$ 600.00	
Check Lightings			\$ 40.00	7
Tuff Kote			\$ 130.00	70
Wheel Alignment			\$ 120.00	0 00
TOTAL LABOUR	2		\$ 1,620.0	0
ESTIMATE TOTA	L		\$ 5,102.0	0
	Front Fender Shield LH Front Fender Retainer LH Front Fender Retainer LH HeadLamp LH Front Wheel Cap LH Front Wheel Rim LH SUB TOTAL LESS 20% DISCOUNTED TOTAL Front Wheel Tyre LH SPARE PARTS TOTAL Labour Charge Panel Beating Spray Painting Charge Check Lightings Tuff Kote Wheel Alignment TOTAL LABOUR ESTIMATE TOTAL	Front Fender LH Front Fender Shield LH Front Fender Retainer LH HeadLamp LH Front Wheel Cap LH Front Wheel Rim LH SUB TOTAL LESS 20% DISCOUNTED TOTAL Front Wheel Tyre LH SPARE PARTS TOTAL Labour Charge Panel Beating Spray Painting Charge Check Lightings Tuff Kote Wheel Alignment TOTAL LABOUR ESTIMATE TOTAL	Front Fender Child LH Front Fender Shield LH Front Fender Retainer LH HeadLamp LH Front Wheel Cap LH Front Wheel Rim LH SUB TOTAL LESS 20% DISCOUNTED TOTAL Front Wheel Tyre LH SPARE PARTS TOTAL Labour Charge Panel Beating Spray Painting Charge Check Lightings Tuff Kote Wheel Alignment TOTAL LABOUR ESTIMATE TOTAL	Front Fender En

After organi photos.

After organi photos.

Grandi of

18/4/22

vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Projudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

-20%: 2600

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process
 This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

ACCIDENT STATEMENT

Date of Submission Date of Accident Exact Location of Accident Additional Location Information Country/State of Loss

16/04/2022 11:20 (SGT) 15/04/2022 23:05 (SGT) Bukit Timah Rd, Singapore

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SH8352P

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No

Yes **COMFORT TRANSPORTATION PTE LTD** 1XXXXXX821R fleetsafety@cdgtaxi.com.sg (Phone) +65-97320297 (Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

Hyundai 140

Private hire

No - Claiming third party

Taxi Auto 1685

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy **Policy Number** Cover Note Number

AXA Insurance Pte Ltd ThirdPartyFireTheft Yes VFX/P2419138

DRIVER

Name of Driver NRIC No

TAN SHUAN LUOH SXXXX539D



Date Of Birth Occupation **Date Of Driving Pass**

Driving experience

Gender

Mobile Number Alt. Phone Number **Email Address**

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

01/10/1957 Outdoor 12/04/1976 46 YEARS

Male (Phone) +65-97320297

fleetsafety@cdgtaxi.com.sg

BLK 496C TAMPINES STREET 43 #11-259

526496

No Hirer

No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Collision - Change/cross lane

Clear Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged?

Number of Passengers (Including Driver) Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

No

No

Yes 2

Nα

PASSENGER 1

Name Gender UNKNOWN Female

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?

No No

CIRCUMSTANCES OF ACCIDENT

ON 15.04.2022 AT ABOUT 2305HRS I WAS DRIVING MY VEHICLE A SH8352P ALONG BUKIT TIMAH ROAD TOWARDS NEWTON CIRCLE. NEAR THE PETROL KIOSK, AS MY VEHICLE A WAS FILTERING INTO THE LEFT LANE, VEHICLE B SJZ1267K ON MY LEFT SIDE, TRAVELLING AT A FAST SPEED SIDE SWIPE HIS RIGHT FRONT ONTO MY VEHICLE A LEFT FRONT, VEHICLE B DID NOT STOP, I CHASED AND HONKED HIM FOR A QUITE A DISTANCE. FINALLY HE STOP SND DECLARED THAT THERE IS NO DAMAGE TO HIS VEHICLE B. NO ONE WAS INJURED AND NO PARTICULARS EXCHANGED

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Was there any audio recorded?

Yes

Yes

FILE IS NOT SUITABLE

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Manufacturer

SJZ1267K



Page 2 of 20

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

Private car

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the dams process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Formity insurance companies is not an admission of policy liability on the part of the insurance companies
- 5 Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Associated of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the loogement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Coment under the Personal Data Protection Act(PDPA)

lunderstand, acknowledge, agree and consent that :

- (a) by insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectivity the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have trained vehicle(s) tracked in this accident (all insurer(s) in ho have insured vehicle(s) involved in this accident (all insurer(s) in ho have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- ssing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- (ii) Investigating the accident and/or my dalms; (iii) carrying out and/or dualing with my instructions or responding to any enquiries by me;
- (N) administrating my datins (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. budy the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (Including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Driver's Signature (If driver is not the policyholder) / Date * Thre 1604.2022 1045HPS Sketch Plan S4 8352P TOWARDS NEWTON CIRCLE ABOVE PORT TO NEWTON PLYOVE BUKIT WHAT ROAD



Describe Circumstances of the Accident

ON 15.04.2022 AT ABOUT 2305HRS I WAS DRIVING MY VEHICLE A SH8352P ALONG BUKIT TIMAH ROAD TOWARDS NEWTON CIRCLE. NEAR THE PETROL KIOSK, AS MY VEHICLE A WAS FILTERING INTO THE LEFT LANE, VEHICLE B SJZ1267K ON MY LEFT SIDE. TRAVELLING AT A FAST SPEED SIDE SWIPE HIS RIGHT FRONT ONTO MY VEHICLE A LEFT FRONT. VEHICLE B DID NOT STOP, I CHASED AND HONKED HIM FOR A QUITE A DISTANCE . FINALLY HE STOP SND DECLARED THAT THERE IS NO DAMAGE TO HIS VEHICLE B. NO ONE WAS INJURED AND NO PARTICULARS EXCHANGED

Declaration