COMFORTDELGRO ENGINEERING

| Our Job Ref No | | | 305512612 | LITOITELIIT | | | 1011 1CERTI 10 |
|------------------------------------------------------|----------------|--------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------|----------------|
| Date | | | 21.04.22 | | ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 | | |
| FINA | LIZATI | ON FORM | | | · | un. 00 10 | 0.00 |
| То | : | | LKK | | Fax: | | |
| Attn : Mr | | | GUO QIANG | | | | |
| Vehicle Reg No. SHA9 | | | 590D | Date | e of Accide | nt : | 14.04.22 |
| The s | urvev : | and estimates of | the repairs of the above-me | entioned vehicle | e are as fo | llows:- | |
| | • | | | | | | 00055004 |
| 1. | The r | epair job shall bil | | NTUC | | | GBB5580A |
| 2. | The f | nalized amount s | shall be: | | | | |
| | (a) | Spare Parts after | er List discount | | | <u></u> | |
| | (b) | Labour Charges | 3 | | | 2 | |
| | | Total for Part-E | By-Part Repair Cost | | | | |
| | (0) | Lumasum Dana | is (if applicable) | | | | |
| | (c.) | | um repair cost after Less: | 20% | | | \$4,250.00 |
| | | Final Lumpsun | n Repair cost | | | | |
| 3. 4. 5. | We si 7 wor | king days you for your ass ture: JUMANI | sistance. | 4 working days. Ind Confirmed if there is no reply from you within We confirm the estimates and finalized amount Signature: Name : GUO QIANG | | | |
| Tel : 6214831 | | | 5 | Date : | | | |
| | Fax | : 6546815 | 6 | | | | |
| For O | fficial | Use Only | | | | | |
| | ı | tem | Amount | Document Attached Yes or No | Confirm (Signatur | | Remarks |
| Rental Rate P/Day | | | | YES | | | |
| 2. Loss of Income Paid | | | (2402) | NO | | | |
| 3. Survey Fees | | | i svita : | | | | |
| LTA Search Fee | | | \$7.49 / \$2.00 | | | | |
| 5. Medical Fees (on behalf of driver, if applicable) | | | | | | | |
| | errun | ii applicable) | | | | | |
| Rema | rks: | | | | | | |