

Your Ref: 17/18/18/VC10/257311

Date: 11<sup>th</sup> May 2022

Our Ref: CS1/LPM22003643/Kqy3e2

**M/s Lonpac Insurance Bhd**

21st Flr, Bangunan Public Bank  
No. 6 Jalan Sultan Sulaiman  
50000 Kuala Lumpur, Malaysia  
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SH 7927M  
INSURED VEHICLE: W 7897E  
ACCIDENT DATE: 17/04/2018**

We thank you for your instruction on 18/04/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 7927M from M/s Vicom Ltd.
- b) Police Report of Vehicles SH 7927M.
- c) Colour damaged vehicle photographs of SH 7927M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 7927M
Make & Model	: Hyundai AE Ioniq HEV FL 1.6 DCT
Year of Registration	: 2021
Chassis Number	: KMHC851CVLU194745
Engine Capacity	: 1580 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.