

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305512864
REGN NO : SHB4019R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.01.2021
DATE/TIME IN : 18.04.2022 10:45
ACCIDENT DATE : 15.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0003 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00

SUB-TOTAL : 435.12

JOB NATURE

0000 PB	PANEL BEATING	600.00
0001 SP	SPRAYPAINT CHARGE	600.00
0002 L	REMOVE/REFIX REVERSE SENSOR	50.00

SUB-TOTAL : 1,250.00

TOTAL : 1,685.12 600

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

2 tangs.
After repair photos
Gang Arp
18/4/22 4:30pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: