

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NOTE (US)

Date: 18.04.2022

Time: 11:20:42

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305512616
 REGN NO : SHC8595L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.12.2015
 DATE/TIME IN : 18.04.2022 09:40
 ACCIDENT DATE : 13.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	DEP PANEL ASSY-RR DR RH#	1	2,416.80	20.00	1,933.44	X	Lynzi
0002 04-01-0103-0575-G	DEP PANEL ASSY-QUARTER OT	1	2,171.40	20.00	1,737.12	X	
0003 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	553.00	20.00	442.40	X	
0004 04-01-0103-0658-G	CAP ASSY-WHEEL HUB	1	214.20	20.00	171.36	—	cut.
0005 05-01-0199-0032-A	WINDSCREEN AHESIVE-310MLC	2 N	46.00	10.00	41.40	X	na
0006 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	—	na
0007 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	1.00-	50.00	X	na
0008 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	X	
0009 04-01-0103-0810-G	DEP MOULDING ASSY-SIDE SI	1	732.80	20.00	586.24	X	


SUB-TOTAL : 5,051.56

JOB NATURE

0000 PB PANEL BEATING
 0001 SP SPRAYPAINT CHARGE

1200.00 ~~560~~ 840

1000.00 750



COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 18.04.2022

Time: 11:20:42

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305512616
REGN NO : SHC8595L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.12.2015
DATE/TIME IN : 18.04.2022 09:4
ACCIDENT DATE : 13.04.2022

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT	
0002 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	200.00	X
0003 L	TRANSFER DOOR PART npa	1.00	X
0004 L	REMOVE/REFIX RR WINDSCREEN GLASS npa	1.00	X
SUB-TOTAL		: 2,402.00	

TOTAL : 7,453.56

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

4 Days.
4s
After repair photos
Gina Q: p
18/4/22
4 pm

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: