

ASS. REC. BY:

REF:

C72/ 22 003656/kv

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJD 4591U

Policy No. DMPCSNA00049812204

Claims No. SNM22D202617/C2/BILLY

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

1.B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SND 6019X

Yr Regn:

01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tesla Model 3

c.c

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

2550

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

LRW3F7FA8MC 416169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/45ZR18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

17/4/22

D.O.I.

20/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rta

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27/5 @ 3887.92 Carhit (red 2564.58m 40%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I: (\$ 3887.92

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
468B

Owner ID:

Vehicle Details

Vehicle No.: SND6019X
Vehicle to be Exported: No
Intended Deregistration Date: 20 Apr 2022
Vehicle Make: TESLA
Vehicle Model: MODEL 3 STANDARD RANGE
Primary Colour: Red
Manufacturing Year: 2021

Engine No.: -
Chassis No.: LRW3F7FA6MC416169
Maximum Power Output: 239.0 kW (320 bhp)
Open Market Value: \$60,553.00
Original Registration Date: 12 Jan 2022
First Registration Date: 12 Jan 2022
Transfer Count: 0

Actual ARF Paid: \$35,996.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Jan 2032
PARF Rebate Amount: \$26,997.00

Intended COE Rebate Details

COE Expiry Date: 11 Jan 2032
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$80,989.00
COE Rebate Amount: \$78,768.00
Total Rebate Amount: \$105,765.00

The information contained herein is correct as at 19 Apr 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	18/04/2022 15:18 (SGT)
Date of Accident	17/04/2022 15:35 (SGT)
Exact Location of Accident	Near 277C Compassvale Link, Singapore 543277
Additional Location Information	Blk 277D Compassvale Link Carpark
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SND6019X
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Wu Xiaodong
NRIC No	SXXXX468B
Email Address	helen6135@hotmail.com
Mobile Phone No	(Phone) +65-98268536
Alternative Phone No	(Home) +65-98268536

VEHICLE PARTICULARS

Manufacturer	Tesla
Model	Model 3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1999

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	SP2000818287-01
Cover Note Number	-

DRIVER

Name of Driver	Wu Xiaodong
NRIC No	SXXXX468B

Date Of Birth	11/11/1982
Occupation	Indoor
Date Of Driving Pass	16/12/2021
Driving experience	4 MONTHS
Gender	Female
Mobile Number	(Phone) +65-98268536
Alt. Phone Number	(Home) +65-98268536
Email Address	helen6135@hotmail.com
Address	Blk 277D Compassvale Link
Address complement	#11-306
Postcode	544277
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Ge Xuanwei Keruby
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 17/04/2022 @ 15:35 HOURS, I WAS AT BLK 277D COMPASSVALE LINK CARPARK, I SAW VEHICLE B: SJD4591U WANTED TO TURN LEFT, SO I MADE WAY BY DRIVING TO THE LEFT SIDE AND STOPPED FOR VEHICLE B: SJD4591U TO PASS. BUT VEHICLE B: SJD4591U MAKE A WIDE TURN AND HIT INTO MY VEHICLE A: SND6019X REAR RIGHT PORTION CAUSING DAMAGE. WE EXCHANGED OUR PARTICULARS. NO ONE WAS INJURED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD4591U
Vehicle Manufacturer	Honda
Vehicle Model	Crossroad

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Vehicle Variant	-
Vehicle Colour	Black
Vehicle Category	Private car
Name of Driver	Leong Meng Wai (Liang Mingwei)
NRIC No	SXXXX164D
Contact Number	(Phone) +65-85690191
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Describe Circumstances of the Accident

PETER TV STATEMENT:

Declaration

We declare the foregoing particulars are true in every respect.

 18/04/22

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Not Notarized
Recovery Bypass
6 days

Date: 18/04/2022
Vehicle No: SND6019X
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA6MC416169-2021
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SJD4591U
Date of Accident: 17/04/2022
Estimator: TING AN
Surveyor:

83887.92

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		R \$953.27
2	REAR DOOR WEATHERSTRIP RH	1		Sm \$88.79
3	REAR FENDER RH	1		Ry \$1,345.77
4	REAR FENDER QUARTER GLASS RH with Midy	1		the \$280.37
5	REAR RIM RH	1	n.c	Red \$467.29
6	REAR RIM COVER RH	1		R \$32.71
7	REAR BUMPER	1		Red / Sm \$663.55
8	REAR BUMPER SIDE BRACKET RH	1		Sm \$7.48
9	REAR BUMPER REVERSE SENSOR	1		Short \$158.88
10	REAR BUMPER REVERSE SENSOR BRACKET	1		the \$4.67
SUB TOTAL				\$4,002.78
LESS 10%				-\$400.28
PARTS TOTAL				\$3,602.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR QUARTER GLASS SEALANT RH	1		the \$80.00
2	REAR BUMPER CLIPS	1		the \$50.00
3	REAR DOOR INNER TRIM BOARD CLIPS RH	1		na \$50.00
S/N TOTAL				\$180.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.

800.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

na \$150.00

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

300.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 18/04/2022
Vehicle No: SND6019X
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA6MC416169-2021
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SJD4591U
Date of Accident: 17/04/2022
Estimator: TING AN
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	50%
LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS RH & ETC.	\$150.00	60%
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	20%
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	90%
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$120.00	20%
LABOUR TOTAL		\$2,670.00

TING AN	TOTAL	\$6,452.50
---------	-------	------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

