

ASS. REC. BY:

REF:

C721

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.B.1%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SND 6019X

Yr Regn:

01, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Testa Model 3

C.C.

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

2550

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LRW3F7FA6MC 416169

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/45 ER18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

17/4/12

D.O.A.

20/4/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

*Not Notation  
Penny Bypass  
6 days*

Date: 18/04/2022  
Vehicle No: SND6019X  
Model: TESLA MODEL 3 STANDARD RANGE  
Chassis: LRW3F7FA6MC416169-2021  
Reg.Year: 2022

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SJD4591U  
Date of Accident: 17/04/2022  
Estimator: TING AN  
Surveyor:

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR DOOR RH	1		<i>R</i> \$953.27 <i>X</i>
2	REAR DOOR WEATHERSTRIP RH	1		<i>Sn</i> \$88.79 <i>A</i>
3	REAR FENDER RH	1		<i>Ry</i> \$1,345.77 <i>✓</i>
4	REAR FENDER QUARTER GLASS RH <i>with Mldy</i>	1		<i>She</i> \$280.37 <i>✓</i>
5	REAR RIM RH	1	<i>n.c</i>	<i>Red</i> \$467.29 <i>X</i>
6	REAR RIM COVER RH	1		<i>R</i> \$32.71 <i>A</i>
7	REAR BUMPER	1		<i>Red / Wn</i> \$663.55 <i>✓</i>
8	REAR BUMPER SIDE BRACKET RH	1		<i>Sn</i> \$7.48 <i>X</i>
9	REAR BUMPER REVERSE SENSOR	1		\$158.88 <i>?</i>
10	REAR BUMPER REVERSE SENSOR BRACKET	1		\$4.67 <i>?</i>
SUB TOTAL				\$4,002.78
LESS 10%				-\$400.28
PARTS TOTAL				\$3,602.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR QUARTER GLASS SEALANT RH	1		<i>Red</i> \$80.00 <i>30m</i>
2	REAR BUMPER CLIPS	1		<i>Red</i> \$50.00 <i>✓</i>
3	REAR DOOR INNER TRIM BOARD CLIPS RH	1		<i>Red</i> \$50.00 <i>X</i>
S/N TOTAL				\$180.00

### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

*600*  
\$800.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC.

*660*  
\$800.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH.

*nn* \$150.00 *X*

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & UPHOLDSTERY CUSHION SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

*100*  
\$300.00

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554600  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011





Date: 18/04/2022  
Vehicle No: SND6019X  
Model: TESLA MODEL 3 STANDARD RANGE  
Chassis: LRW3F7FA6MC416169-2021  
Reg. Year: 2022

Third Party Insurer: CHINA TAIPING  
Third Party Veh No: SJD4591U  
Date of Accident: 17/04/2022  
Estimator: TING AN  
Surveyor:

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	\$120.00	501
LABOUR CHARGES TO REMOVE & REFIX REAR QUARTER GLASS RH & ETC.	\$150.00	601
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	201
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	7
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$120.00	201
LABOUR TOTAL		\$2,670.00

TING AN

TOTAL

\$6,452.50

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission 18/04/2022 15:18 (SGT)  
Date of Accident 17/04/2022 15:35 (SGT)  
Exact Location of Accident Near 277C Compassvale Link, Singapore 543277  
Additional Location Information Blk 277D Compassvale Link Carpark  
Country/State of Loss Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SND6019X  
INSURED/POLICYHOLDER  
Is company? No  
Name Of Registered Owner Wu Xiaodong  
NRIC No SXXXX468B  
Email Address helen6135@hotmail.com  
Mobile Phone No (Phone) +65-98268536  
Alternative Phone No (Home) +65-98268536

## VEHICLE PARTICULARS

Manufacturer Tesla  
Model Model 3  
Variant -  
Exact purpose for which vehicle was being used at time of accident Private use  
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party  
Vehicle Category Private car  
Transmission Auto  
CC 1999

## INSURANCE COMPANY

Name of Insurance Company Allianz Insurance Singapore Pte. Ltd.  
Type of Coverage Comprehensive  
Fleet Policy No  
Policy Number SP2000818287-01  
Cover Note Number -

## DRIVER

Name of Driver Wu Xiaodong  
NRIC No SXXXX468B



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*[Signature]*

18/04/20

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

### Sketch Plan

