



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CS/EQI22003665/Uny3e2 Date: 12/07/2022 Code: EQI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SMU 3894C	Veh. Inspected	SJJ 1321X	
Policy No.	DMPPHQ22-000178	Coverage (\$)	0.00	
Claim No.	DM22HO00569	Excess (\$)	0.00	
Assign From	NEO JIE SI	Assign Date	14/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN X-TRAIL (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JN1JANT32Z0001145	Colour	WHITE	
Odometer	67385 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/60 R18	YOKOHAMA	6 mm	
L/H Front Tyre	225/60 R18	YOKOHAMA	6 mm	
R/H Rear Tyre	225/60 R18	YOKOHAMA	6 mm	
L/H Rear Tyre	225/60 R18	YOKOHAMA	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/04/2022	Inspection Date	21/04/2022	
Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	