



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22003667/Uqy3m4 Date: 16/06/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMC 4788P	Veh. Inspected	SLJ 1675B	
Policy No.	D21MTPV01010679	Coverage (\$)	0.00	
Claim No.	CMTD2201333/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW 116D (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA1V720705C07743	Colour	BLACK / BLUE	
Odometer	136026 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/50 R17	MICHELIN	7 mm	
L/H Front Tyre	215/50 R17	MICHELIN	7 mm	
R/H Rear Tyre	215/50 R17	YOKOHAMA	7 mm	
L/H Rear Tyre	215/50 R17	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/04/2022	Inspection Date	21/04/2022	
Survey held at	BLK 15 KAKI BUKIT ROAD 4 #01-53 S'PORE (417808)			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	