

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO22003671/Kty3e2	
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623		Date:	06/05/2022	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMH 6335Z	Veh. Inspected	b	SNA 7584P	
	Policy No.	D21MTPV01008072	Coverage (\$)		0.00	
	Claim No.	CMTD2201302/AGC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		20/04/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA ALTIS (A)	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	MR053REH104540578	Colour		METALLIC GREY	
	Odometer	111640 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	BRIDGESTONE		2 mm	
	L/H Front Tyre	215/45 R17	BRIDGESTONE		2 mm	
	R/H Rear Tyre	215/45 R17	BRIDGESTONE		2 mm	
	L/H Rear Tyre	215/45 R17	BRIDGESTONE		2 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
5.	5. General Information					
	Accident Date	18/04/2022	Inspect Date /	Time	21/04/2022 (09:49 AM)	
	Survey held at	KING'S AUTO REPAIR & SERVI	CE PTE LTD			
	176 SIN MING DRIVE, #02-10, SIN MING AUTOCARE, SINGAPORE 575721					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/SMO22003671/Kty3e2

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser