



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003673/Eqy3n2	Date: 23/05/2022
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SGK 5649E	Veh. Inspected	PA 6977Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014756/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI MD RABU	Assign Date	20/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	ISUZU LT134P	c.c	7790	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JALLT134P77000070	Colour	MULTI COLOUR	
Odometer	340459 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Front Tyre	295/80 R22.5	DUNLOP	4 mm	
R/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
L/H Rear Tyre	295/80 R22.5	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/04/2022	Inspection Date	22/04/2022	
Survey held at	566 WOODLAND ROAD S728697			
Repairer	CONNECT3			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	