



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22003676/Uvy3n2	Date: 20/05/2022
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJQ 7328B	Veh. Inspected	SLQ 8898S	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10014839/JM	Excess (\$)	0.00	
Assign From	SHAFAWATI	Assign Date	20/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ACCORD (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHCR1630GP000051	Colour	SILVER	
Odometer	109152 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	MICHELIN	8 mm	
L/H Front Tyre	225/45 R17	MICHELIN	8 mm	
R/H Rear Tyre	225/45 R17	MICHELIN	8 mm	
L/H Rear Tyre	225/45 R17	MICHELIN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/04/2022	Inspection Date	20/04/2022	
Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	