

(08/11/11)

ASS. REC. BY: theyan

REF: CS/11/22003688/0043

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SH68 SH6501K Yr Regn: 2014/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /

Truck / Trailer or

Make: Toyota prius hybrid c.c 1798

Colour: blue A/C: Insured / Std / NI / NA

Sp. Reading: not avail T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3TDH3F4703091135

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 20/4/22 D.O.I. 21/4/22 1700

Survey held at CDGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS. ____ SI

Photos

Others

TOTAL

Date/Time: 21.04.2022 08:20 Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4199337 JC NO 305513195

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO	SH 6580K	MILEAGE
MAKE	TOYOTA	FUEL
MODEL	PRIUS HYBRID(G4A20)	DATE/TIME IN
YR OF MANUF	28.02.2020	TARGET DATE
CHASSIS CODE	JTDKKB3FU703091135	COMPLETION DATE/TIME


UNT CARD NO

cident Date: 20.04.2022
TURE: 3P 20.04.2022

JOB DESCRIPTION

NO 0010 LABOR CODE PB

DESCRIPTION
PANEL BEATING-SH 6580K-TP



ED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

dgement Slip

Exit Pass

SH 6580K LIMITS

Vehicle No.: SH 6580K

Service Advisor Signature/Date

Name of Service Advisor Date

rned to Service Reception upon collection

To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd

401 LOYANG DRIVE
SINGAPORE 630000
Tel: 6754 8300

Lim Tien Siong

TP INSURER:
CTPL

India International Insurance Pte Ltd (HQ)

CP(P)

Singapore

LKK-

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/04/2022
Vehicle Reg. No.:	SH6580K	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	28/02/2020
Vehicle Colour:	BLUE	Chassis No:	JTDKB3FU703091135
Engine No:	2ZR2G74578		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,550.16
Miscellaneous Items	11.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,141.16
+ GST 7.00% (S\$)	219.88
Nett Amount (S\$)	3,361.04

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2022) Lim Tien Siong
Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SH6580K/21/04/2022 08:26
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER	25.00	0.00	*591.75 FL <i>DT</i>
2	10		*FRT BUMPER CLIPS	25.00	0.00	*22.00 FL <i>na</i>
3	1		*FRT BUMPER BRKT RH	25.00	0.00	*77.00 FL <i>na</i>
4	1		*FRT FENDER RH	25.00	0.00	*1,111.93 FL <i>xr</i>
5	1		*FRT FENDER (HYBRID) RH	25.00	0.00	*86.50 FL <i>na</i>
6	1		*FRT WHEEL CAP RH	25.00	0.00	*177.70 FL <i>SC</i>
Sub Total (\$\$)						2,066.88
- List Item Discount on L Items (\$\$)						516.72
Total Parts (\$\$)						1,550.16

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SH6580K/21/04/2022 08:26. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

4/21/22, 8:26 AM

Merimen e-Claims

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

800.00

2 SPRAY PAINTING

New

600.00

3 TUFF KOTE

New

60.00

4 WHEEL ALIGNMENT

New

120.00

Gross Labour Cost (S\$)

1,580.00

ComfortDelGro Engineering Pte Ltd/SH6580K/21/04/2022 08:26. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan

82235769

21/4/22 1700

p/p 3dayswp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date