

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Apr 2022 <a href="#">Sendback Est</a>	21 Apr 2022 08:53 <b>S\$ 3,350.04</b>	21 Apr 2022 14:09 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

### CLAIM SUBFOLDER DETAILS

Insured:	HONG WAI MEI , ID : S7240931J , Tel: +6598290284 , Email: ashlee.tan@gmail.com		
Main Claimant:	CTPL		
Vehicle Reg. No.:	SHC8466B	Date of Loss :	20/04/2022 00:00 - :59 [27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2201883	Policy/Cover Note No. :	MU001138 (Comprehensive) Coverage: 01/02/2022 - 31/01/2023
Vehicle Reg. No. (Insured):	SJF8881X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Tan Siok Thiew Jas]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Thevan Thomas Karthikesavan] ... [Final Rpt due 02/05/2022]		

### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### ALL ASSOCIATED FILE NOTES

[Create New](#)

No.	Status	Type	Viewer/ Assigned To	Note	Created On	Created By	1st Read By
No results.							

### ADJUSTER'S CLAIM REFERENCE

Assignment From:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b>		
Adj File Ref No:	CS/TMI22003703/VQY3	Assignment Date:	21/04/2022
Inspection / Investigation Date:		Report Date:	
Insurance Claim No:	M2201883	Recmd'd Resv. (S\$):	
Manager:	SHIAU CHAN	Adjuster:	Thevan Thomas Karthikesavan
Clerical:	(First Pick-up)		
Present Vehicle Loc.:	ComfortDelGro Engineering Pte Ltd (Loyang) (from est.) (Check-in: 21/04/2022)		

### DESCRIPTION OF VEHICLE

Vehicle Model:	<b>TOYOTA PRIUS 1.8 HYBRID CVT (A)</b>		
Engine No:	L15B4531706	Chassis No:	JHMRU1810GX201707
LTA Reg Date (Man Yr):	24/03/2022 (2022)		
Colour of Vehicle:	Blue	Odometer Reading:	0 km

### CLAIM LOSS DETAILS

Police Report No (Date):		Party At Fault:	Unknown
Collision With:	Private Vehicle	Nature of Loss:	
Description of Accident/Loss:	ACCIDENT INVOLVING SJF8881X & SHC8466B ALONG DOVER ROAD		

DOCUMENTS CHECKLIST

All Completed Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

DOCUMENTS SUMMARY

Assessment Reports

- ComfortDelGro Engineering Pte Ltd (Loyang) [Thumbnails]:(21/04/22) Repairer Estimates

Documentation

- ComfortDelGro Engineering Pte Ltd (Loyang) [Thumbnails]:(21/04/22) E-filed GIA report