

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305513135
 REGN NO : SHC1041P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 03.09.2018
 DATE/TIME IN : 20.04.2022 09:20
 ACCIDENT DATE : 19.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2534-G COVER-FR BUMPER# *X repair* 1 481.10 20.00 384.88

0002 04-01-0104-2361-G MOULDING-FRONT BUMPER CTR 1 368.50 20.00 294.80 */ RT*

0003 04-01-0104-2915-A LAMP ASSY-HEAD RH# 1 2,110.30 20.00 1,688.24 *- CRA*

0004 04-01-0104-3918-G BRACKET-FR BUMPER SIDE RH 1 28.00 20.00 22.40 *X NN*

SUB-TOTAL : 2,390.32

2478.8

JOB NATURE

-20%: 1983.04

0000 PB PANEL BEATING

400.00 *350*

0001 SP SPRAYPAINT CHARGE

300.00 *250*

0002 17-01 CHECK ALL LIGHTING

50.00 *20*

2603.04

SUB-TOTAL : 750.00

-20%: 2100

TOTAL : 3,140.32

Jurnal:

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

*2 Days.
 45
 After mpris photos.
 One Q: 4
 20/4/22 gpm*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party's liability on "Without Prejudice" basis
- No illegal modification to vehicle
- Supplementing any damaged parts surveyed and is subject to the approval of Insurance Company

Acknowledged by: _____
 Signed: _____
 Date: _____