

Our Job Ref No : 305512226  
Date 19.04.22

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK

Fax :

Attn : Mr THEVAN

Vehicle Reg No. SHC1288U

Date of Accident : 11.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBL5984R
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$1,600.00  
**Final Lumpsum Repair cost**
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.


We confirm the estimates and  
finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : THEVAN

Date : 26/4/22

### For Official Use Only

| Item   | Amount          | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|--|-----------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |                 | YES                         |                        |         |
| 2. Loss of Income Paid                               | ----            | NO                          |                        |         |
| 3. Survey Fees                                       | ----            | ---                         |                        |         |
| LTA Search Fee                                       | \$7.49 / \$2.00 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |                 |                             |                        |         |
| 6. Overrun   |                 |                             |                        |         |

Remarks:

\_\_\_\_\_

REC

NAME (4S)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 13.04.2022

REPAIR ESTIMATE

Time: 09:46:46

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305512226  
 REGN NO : SHC1288U  
 MILEAGE : 0000000000  
 MAKE : TOYOTA  
 MODEL : PRIUS HYBRID(G4)  
 DATE OF REGN : 19.07.2017  
 DATE/TIME IN : 13.04.2022 09:10  
 ACCIDENT DATE : 11.04.2022

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-0593-G PANEL SUB-ASSY FRONT DOOR 1 1,264.00 25.00 948.00 *XV*  
 0002 28-01-0103-0003-A FRT DOOR LOGO CTPL 1 N 75.00 10.00 67.50 *N/C*  
 0003 28-01-9999-2023-A APP LOGO REAR DOOR L/R CT 1 N 80.00 10.00 72.00 *N/C*

SUB-TOTAL : 1,087.50

## JOB NATURE

0000 PB PANEL BEATING 600.00 *350*  
 0001 SP SPRAYPAINT CHARGE 600.00 *500*  
 0002 L TRANSFER DOOR PART 120.00 *XNN*

SUB-TOTAL : 1,320.00

TOTAL : 2,407.50

Jumari:

MVA NAME & SIGNATURE  
 DATE:

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE:

*Thuan*  
*82235469*  
*13 4/24/22*  
*1700*  
*4S repair & delay sup*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer