

ASS. REC. BY: ThevanREF: ntac**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC12884 Yr Regn: 19/7/17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Toyota Prius hybrid c.c. 1798Colour: 753364 blue A/C: Insured / Std / NI / NASp. Reading: 753364 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STD1B3Fu303560463Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 11/4/22 D.O.I. 13/4/22 1700Survey held at CDGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	No GIA provided

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS _____ \$

Photos _____

Others _____

TOTAL _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Date/Time: 13.04.2022 09:48

Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4196339

JC NO.:305512226

OMER

COMFORT TRANSPORTATION PTE LTD
 7010045
 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65508755
 (R) (P) (O)


REGN NO. SHC1288U	MILEAGE
MAKE TOYOTA	FUEL E..... 1/2..... F
MODEL PRIUS HYBRID(G4)13.	DATE/TIME IN 04.2022 09:10
YR OF MANU 19.07.2017	TARGET DATE
CHASSIS CODE JTDKB3FU303560463	COMPLETION DATE/TIME:

QUINT CARD NO.

JOB DESCRIPTION

ccident Date: 11.04.2022
 ATURE: 3P.11.03.2022

/NO	LABOR CODE	DESCRIPTION
00040	PB	PANEL BEATING
00050	SP	SPRAYPAINT CHARGE
00060	L	TRANSFER DOOR PART



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHC1288U JU NTUC

Vehicle No.: SHC1288U

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

NTUC (4S)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 13.04.2022
Time: 09:46:46
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305512226
REGN NO : SHC1288U
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 19.07.2017
DATE/TIME IN : 13.04.2022 09:10
ACCIDENT DATE : 11.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-0593-G PANEL SUB-ASSY FRONT DOOR 1 1,264.00 25.00 948.00 *KV*
0002 28-01-0103-0003-A FRT DOOR LOGO CTPL 1 N 75.00 10.00 67.50 *N/C*
0003 28-01-9999-2023-A APP LOGO REAR DOOR L/R CT 1 N 80.00 10.00 72.00 *N/C*

SUB-TOTAL : 1,087.50

JOB NATURE

0000 PB PANEL BEATING 600.00 *350*
0001 SP SPRAYPAINT CHARGE 600.00 *500*
0002 L TRANSFER DOOR PART 120.00 *XNN*

SUB-TOTAL : 1,320.00

TOTAL : 2,407.50

Juman:

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Theran
82235469
13 4/24/22
1700
4S repair 2 days sup

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer